

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE *
(Other Instructions on
reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐ WIW

2. NAME OF OPERATOR
The Wiser Oil Company

3. ADDRESS OF OPERATOR
P.O. Box 2568 Hobbs, New Mexico 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
2080' FNL & 1980' FEL
Unit G

5. LEASE DESIGNATION AND SERIAL NO.
NM-98122

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Skelly Unit

8. WELL NAME AND NO.

65

9. API WELL NO.

30-015-05342

10. FIELD AND POOL, OR WILDCAT
Grayburg Jackson 7-Rivers QN-GB-SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 21-T17S-R31E

14. PERMIT NO

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3812' DF

12. COUNTY OR PARISH
Eddy County

13. STATE
NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT * ☐
(Other) Clean Out & Repair Zone
(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10/23/03 MIRU Eunice Well Service. ND WH. RU BOP. Unset pkr. POH w/2-3/8" IPC tbg. LD 5-1/2" Baker J-Lok pkr. RIH w/4-3/4" cone bit on 2-3/8" work string. Tag @ 3089'. POH w/tbg. & tools. RIH w/4-3/4" bit & DC's on 2-3/8" work string. Tag @ 3089'. Pull up to 3000'.

10/24/03 Tag fill @ 3089'. Drill to 3490'. Circulate hole clean. LD 2-3/8" work string & tools. RU Computalog WL & perforate Grayburg San Andres f/3105'-12', 22'-26', 35'-40', 3213'-14', 28'-33', 41'-44', 70'-80', 3301' & 12'-25' w/4 SPF. RD WL. RIH w/5-1/2" AD-1 pkr., 4 jts. 2-3/8" IPC-EPC tbg., 5-1/2" tandem tension pkr., & 95 jts. 2-3/8" IPC tbg. Top pkr. @ 2958'. Bottom pkr. @ 3087'. RD BOP. NU WH. Circulate 75 bbls. pkr. fluid. Set pkr. Ran casing integrity test to 500# for 30 min. Performed by Nick Jimenez w/Gandy Corporation. Place well back to injection 100 BWPD @ 1240#. RDMO.

10/27/03 RU Eunice Well Service. ND WH. RU BOP. POH w/2-3/8" tbg. LD pkr. Found bottom pkr. sheared. RIH w/redressed 5-1/2" AD-1 pkr., 4 jts. 2-3/8" IPC-EPC tbg., 5-1/2" tandem tension pkr., 95 jts. 2-3/8" IPC tbg. Top pkr. @ 2958'. Bottom pkr. @ 3087'. RD BOP. NU WH. Circulate 75 bbls. pkr. fluid. Set pkr. w/15,000# tension. Ran casing integrity test to 500# for 30 min. Performed by Nick Jimenez w/Gandy Corporation. Place well back to injection - 100 BPWD @ 1260#.

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turner TITLE Production Tech II DATE October 28, 2003

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Accepted for record - NMOCN

*See Instruction On Reverse Side



