

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-103  
May 27, 2004

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-22593
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator BP America Production Company		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 1089 Eunice NM 88231		7. Lease Name or Unit Agreement Name: Empire Abo Unit 'J'
4. Well Location Unit Letter <u>G</u> : <u>1900</u> feet from the <u>N</u> line and <u>2441</u> feet from the <u>E</u> line Section <u>6</u> Township <u>18S</u> Range <u>28E</u> NMPM County <u>EDDY</u>		8. Well Number 234
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3688.6' RKB		9. OGRID Number 00778
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10. Pool name or Wildcat Empire Abo

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11/13/08: PICKUP HEAD TO WASH OVER RBP. PICKUP 80 JT OF TBG AND RIH AND TAGUP AT 2522. CIRC 70 BBLS OF WATER. TAGUP ON PLUG 2556. POH W/ TBG AND WASH OVER HEAD. RIH W/ TBG & ON/OFF TOOL & LATCH ON TO RBP. RELEASE RBP WATCH TBG & CSG TBG ON VAC. POH W/ 1 STAND & THE WELL STARTED TO FLOW. HOOK TBG UP TO PIT & LET IT FLOW ABOUT 5 BBLS & GAS. WENT TO KILL TBG PUMP 15 BBL & STARTED CIRC WELL. PUMP 35 BBLS AROUND AND WATCH WELL FOR 10 MIN NO FLOW. POH W/ RBP AND LAYDOWN. RIH W/ ON/OFF TOOL TO 2560.

Continued on page 2.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed/closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Barry C. Price TITLE Area Operations Team Lead DATE 11/25/08

Type or print name Barry C. Price

E-mail address: barry.price@bp.com

Telephone No. 575-394-1648

For State Use Only

Accepted for record

APPROVED BY NMOCD

TITLE DATE 12/3/08

Conditions of Approval, if any:

Approved for plugging of well bore only.  
This entry under bond is retained pending receipt  
of C-103 (Subsequent Report of Well Plugging)  
which may be found at OCD Web Page under  
Forms: [www.emnrd.state.nm.us/oed](http://www.emnrd.state.nm.us/oed).

Form C-103  
Empire Abo Unit J-234  
30-015-22593  
Continued from Page 1

11/18/08: RIH WITH TUBING, RIH TO 3910' TAG UP PLUG AT 3910' 460' BELOW. TEST CASING TO 500# AT 3910' TEST GOOD. WAIT ON ORDERS TAG PLUG TO LOW. CIRC WELL HAD SOME CEMENT NOT SOLID CIRC CLEAN. WAIT ON MUD TO CIRC BACK AROUND WELL TO REPLACE MUD WE CIRC OUT.

11/19/08: CIRC 100 BBLs OF MUD POH WITH TUBING TO 3723 SPOT 25 SX PLUG. LAYDOWN 10 JTS AND STAND BACK 10 STANDS. WOC.

11/20/08: RIH WITH TUBING AND TAG UP AT 3500. 50' BELOW. CALLED PHIL HAWKINS WITH OCD AND HE SAID IT WAS GOOD. POH WITH TUBING AND IT WAS WET. RIGUP AND TRY TO PUMP COULD NOT TUBING WAS PLUGGED. POH AND WITH TUBING LAYDOWN 13 JOINT THAT WAS PLUG AND THE SEAT NIPPLE HAD MUD AND CEMENT MIX IN IT. RIH WITH TUBING TO 1310 AND SPOT A 25+ SX OF CEMENT. WOC. RIH WITH TUBING AND TAGUP AT 900' POH WITH TUBING.

11/21/08: ND BOP. RIH WITH TUBING TO 600'A. PUMP CEMENT TO SURFACE POH WITH TUBING LAYDOWN. TOP OFF HOLE. RDPU.

11/25/08: DIG OUT, CUT OFF WELLHEAD, WELD IN PLATE, 1" NIPPLE & VALVE, DRY HOLE MARKER, DIG OUT AND CUT OFF ALL ANCHORS, BACKFILL & LEVEL LOCATION.