DEC - 1 2008

OCD-ARTESIAForm C-103 Subtitit 3 Copies To Appropriate District State of New Mexico May 27, 2004 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N French Dr., Hobbs, NM 88240 30-015-29776 District 11 OIL CONSERVATION DIVISION 1301 W Grand Ave, Artesia, NM 88210 5. Indicate Type of Lease District III · 1220 South St. Francis Dr. STATE X FEE 1000 Rio Brazos Rd , Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S St Francis Dr, Santa Fe, NM V-4070 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Southern Cross 16 State PROPOSALS) 8. Well Number 1 Gas Well X Other 1. Type of Well: Oil Well 2. Name of Operator 9. OGRID Number Mack Energy Corporation 013837 I 0. Pool name or Wildcat 3. Address of Operator P. O. Box 960 Artesia, NM 88211-0960 Penasco Draw; Permo Penn 4. Well Location 1650 990 West South Unit Letter feet from the line and feet from the line 16 18S 24E Eddy Section Township Range **NMPM** County I 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3800' GR Pit or Below-grade Tank Application or Closure _Depth Groundwater__ _Distance from nearest fresh water well______ Distance from nearest surface water_ Pit Liner Thickness: Below-Grade Tank: Volume bb1s: Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **CHANGE PLANS** COMMENCE DRILLING OPNS. P AND A TEMPORARILY ABANDON □ MULTIPLE COMPL CASING/CEMENT JOB PULL OR ALTER CASING OTHER: -OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Notify OCD 24 hours prior to starting plugging operations 1) Set CIBP @ 5950' w/ a 35' cmt cap. Notify OCD 24 hrs. prio 2) RIH w/ cmt bond log and find TOC (est TOC 5750'), cut 4 1/2" 11.6# N-80 csg, POH. To any work done. 3) Set cmt plug 50' inside and 50' above casing cut-off point. (tag) 4) Set 100' (27sx) cmt plug from 5070'-4970' (top of Wolfcamp) 5) Set 100' (27sx) cmt plug from 3800'-3700' (top of Abo) 6) Set 100' (30sx) cmt plug from 1256'-1156', WOC tag (9 5/8" csg shoe) 7) Set 75' (25sx) cmt plug from 75' to surface 8) Install P & A Marker Note: Circ. well with salt gel mud consisting of at least 9.5# Brine with 25 pounds of gel per barrel after the bottom plug is set. Approval Granted providing, work is complete by. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will-be-constructed or closed according to NMOCD guidelines ___, a general permit ___ or an (attached) alternative OCD-approved plan ___ TITLE Production Clerk SIGNATURE¹ _DATE 10/1/08 Type or print name Jerry W. Sherrell E-mail address: jerrys@mackenergycorp.com Telephone No. (575)748-1288 For State Use Only APPROVED BY: Conditions of Approval (if any):

Mack Energy Corporation Southern Cross 16 State #1 30-015-29776

Before After

