Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA STATES March 31, 2007

5 Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS				NMLC057798			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7 If Unit or CA/Agreement, Name and/or No NMNM70925X			
1 Type of Well				9. Well Name	and No		
X Oil Well Gas Well Other				8 Well Name and No. Riverwolf 13			
2 Name of Operator							
BP America Production Company		Lat at 11 to 1		9. API Well No)		
3a. Address		3b Phone No. (include area code)		30-015-00629			
P.O. Box 1089 Eunice NM 88231		575 - 394 - 1648		10 Field and Pool, or Exploratory Area			
4 Location of Well (Footage, Sec., T, R, M., or Survey	Description)			Empire Abo			
UL P, 330 FSL & 480 FEL					11 County or Parish, State		
SECTION 35, T17S, R27E							
		·		<u>Ed</u> dy	NM_		
12. CHECK APPROPRIATE	BOX(ES) TO IND	DICATE NATURE OF I	NOTICE, REI	PORT, OR OTH	HER DATA		
TYPE OF SUBMISSION	TYPE OF ACTIO				N		
Notice of Intent	Acidize	Deepen	Producti	on (Start/Resume)	Water Shut-Off		
W a s	Alter Casing	Fracture Treat	Reclama	tion	Well Integrity		
X Subsequent Report	Casing Repair	New Construction	Recomp	lete	Other		
□ · ·	Change Plans	X Plug and Abandon	Tempora	rily Abandon			
Final Abandonment Notice				•			
	Convert to Injection	on Plug Back	Water D	isposai			
12/17/08: TEST TBG. 500 PSI OK. P 12/18/08: CK WELL BLED DN CSG. PU CHANGED OIL IN PULLING UNIT. PUMP 12/19/08: CHECK WELLHEAD PRESSURE J-55 PROD TBG. LD, TAC, SN, PS AN BBLS. OF 9.5 PPG WBM. 12/22/08: PUMP A 25 SXS (CLASS C LD 68- JTS. OF TBG. PUMP A 25 SXS RUNNING TOOL. WOC. RIH W/ TBG. AN 12/23/08: MAKE WIRELINE RUN W/ A RU FLOWBACK LINE ON THE 8-5/8" CS 8-5/8" ANNULUS. UNABLE, MAX PRESS @ 1,120 & PERF 5-1/2" CSG @ 150' OF TBG @ 1,187'. PUMP A 25 SXS BA	MPED 35 BBLS BR ED 40 BBLS DN. , TBG- ZERO & C D 12-JTS. OF TB NEAT) CMT PLUG BALANCED CMT P D TAG TOC @ 3,0 4SPF PERF GUN & G AND TREATING - 1400 PSI. RICL & CIR A SURFACE	CSG. N/D WH N/U BOINGSG- 5 PSI, PUMP 30 G. RIH W/ 5.5" CIBINGS 5 LUG, 3,250- 3200'. 15'. PULL AND LD AING PERF THE 5-1/2" CSULINE TO THE 5-1/2" HARD CARRASCO/BLM (CMT PLUG. RU TBG S	P R/U FLOOF BBLS. OF E BBLS. OF E B & SET @ 5 .350'. TEST PULL TBG. L TBG. CSG @ 1,120' CSG. ATTEN GAVE APPROV STRIPPER. F LL/LD 20-	R TO POOH W/ BRINE DOWN CS 5,350 MD. DIS CCSG. TO 500 LD 10- JTS. POOH, ALL MPT TO BREAK VAL TO SET BA RIH W/39 JTS OF TBG. W	TBG. SG. PULL 2-3/8 SPLACE CSG W/ O PSI. PULL TBG OF TBG AND CII SHOTS FIRED. CIR IN 5-1/2" ALANCED CMT PLI OF TBG. BOTTON	", 123 G & BP X UG M	
CONTINUED ON PAGE 2.		FOR RECORD	Lighi	lity under bond ce restoration is	is retained units		
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Bayry C. Price		Title	perations [†]	Team Lead			
R. P.	JAN 2	1 5009				7	
Dany C- hi	Gerry Guye, Der	Date 01/08/09		APPR	<u>OVED</u>	┷	
// THIS	SPACE CORPE	FRAL OR STATE OF	FICE USE				
Approved by		Title		JAN Da	^{11e} 7 2009		
Conditions of approval, if any, are attached Approval o				UAII '	. 2000	+	
certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations the		ect lease					
		1		IAMES	AMOS		

Title 18 U S C Section 1001, and Title 43 U.S C Section 1212, makes it a crime for any person knowingly and willfully to make to his department of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Form 3160-5 Riverwolf #13 30-015-00629 Continued from Page 1

12/24/08: RIH W/ TBG AND TAG TOC @ 930'. PULL AND LD ALL TBG. MAKE WIRELINE RUN W/ A 4SPF PERF GUN AND PERFORATE THE 5-1/2" CSG @ 150'. POOH, ALL SHOTS FIRED. RD E-LINE UNIT. BREAK CIR IN THE 5-1/2" X 8-5/8" ANNULUS. RD FLOOR, ND BOPE AND NU WELLHEAD FLANGE. PUMP A 40 SXS SURFACE CMT PLUG.

01/06/09: DIG OUT AND CUT OFF WELLHEAD, WELD IN PLATE, 1" NIPPLE & VALVE, DRY HOLE MARKER, DIG OUT AND CUT OFF ALL ANCHORS, BACK FILL AND LEVEL LOCATION.