

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

OCD-ARTESIA
FEB - 3 2009

FORM APPROVED
OMB NO 1004-0135
EXPIRES: March 31, 2007

SUBMIT IN TRIPLICATE

1a. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other _____

2. Name of Operator

DEVON ENERGY PRODUCTION COMPANY, LP

3. Address and Telephone No

P O. Box 250

Artesia, NM

4. Location of Well (Report location clearly and in accordance with Federal requirements)*

1450, FSL & 1980, FEL, J, Sec. 9, T23S R31E

5. Lease Serial No.

NMNM77046

6 If Indian, Allottee or Tribe Name

7 Unit or CA Agreement Name and No

8 Well Name and No

North Pure Gold 9 Federal # 10H

9 API Well No

30-015-36377

10. Field and Pool, or Exploratory

Los Madanos; Delaware

11 County or Parish State

Eddy County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☒ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other _____

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepens directionally or recompletes horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

This location has been cleaned, cut back, reclaimed and is ready for inspection.

14 I hereby certify that the foregoing is true and correct

Signed

Jerry Chaney

Name

Jerry Chaney

Title

Assistant Foreman

Date

1/6/2009

(This space for Federal or State Office use)

Approved by

Title

Date


Conditions of approval, if any:

Title to 5 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations to any matter within its jurisdiction

*See Instruction on Reverse Side

* Seeding Scheduled for Spring

FOR RECORDS ONLY





United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St.
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm



In Reply Refer To: 1310
NMNM77046

November 5, 2008

CERTIFIED-RETURNED RECEIPT REQUESTED
7005 3110 0000 1062 3252

RECEIVED

NOV 07 2008

Devon Energy
P.O. Box 250
Artesia, NM 88210

RE: NMNM77046; North Pure Gold 9 Federal #10H
1450' FSL, 1980' FEL, Sec. 9, T23S-R31E
Eddy County, New Mexico

On November 4, 2008, the Bureau of Land Management (BLM) completed a field inspection on the above referenced well. 43 CFR 3162.5-1(b), states, "Upon conclusion of operations, the operator shall reclaim the disturbed surface in a manner approved or reasonably prescribed by the authorized officer." The objective for interim reclamation is to minimize the environmental impacts of development on other resources and uses.

Earthwork for interim reclamation must be completed within 6 months of well completion (Onshore Oil and Gas Order Number 1). The well to date has not been completed. The interim reclamation is to be completed by May 05, 2009. Upon completion of interim reclamation operations, the operator must submit a sundry to the BLM using Form 3160-5, when the location is ready for inspection. Final abandonment will not be approved until the surface reclamation work required in the Surface Use Plan of Operations or Subsequent Report of Plug and Abandon has been completed to the satisfaction of the BLM.

Contact Bob Ballard at 575-234-2230 prior to starting, prior to removing equipment and seeding.

Sincerely,

Bob Ballard

Bob Ballard
Environmental Protection Specialist

Orig. Vivian
cc: Jerry Mathews
Tracy Kidd
11-18-08
yz