MAR 03 2009

Submit 2 Copies To Appropriate District State of New Mexico	Form C-103
Office <u>District I</u> Energy, Minerals and Natural Resources	October 25, 2007 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave. Artesia, NM 88210 OIL CONSERVATION DIVISION	30-005-63125
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd, Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr, Santa Fe, NM 87505	VA-0582
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Ziggy ARC State
1. Type of Well: Oil Well Gas Well X Other PA	8. Well Number #1
2. Name of Operator	9. OGRID Number
Yates Petroleum Corporation 3. Address of Operator	025575 10. Pool name or Wildcat
105 S. 4 th Street, Artesia, NM 88210	Coyote Queen
4. Well Location	
Unit Letter B: 990 feet from the North line and 2310 feet from the East 1	ine
Section 12 Township 11S Range 27E NMPM Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	Sec. 1
11. Elevation (Snow whether DR, IAD, R1, OR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other I	Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	K ☐ ALTERING CASING ☐ 1
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	
PULL OR ALTER CASING : MULTIPLE COMPL CASING/CEMEN	I JOB
	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in	
	A DEED ON A DEED A OCCUPYON OF
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has	heen cleared of all unk trash flow lines and
,	been cleared of an junk, trash, now fines and
other production equipment.	•
Anchors, dead men, tie downs and risers have been cut off at least two feet below grounds.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground. If this is a one-well lease or last remaining well on lease, the battery and pit location(s	have been remediated in compliance with
Anchors, dead men, tie downs and risers have been cut off at least two feet below groups. If this is a one-well lease or last remaining well on lease, the battery and pit location (s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location.	have been remediated in compliance with luction equipment and junk have been removed
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location (s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.	have been remediated in compliance with luction equipment and junk have been removed
Anchors, dead men, tie downs and risers have been cut off at least two feet below groups. If this is a one-well lease or last remaining well on lease, the battery and pit location (s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location.	have been remediated in compliance with luction equipment and junk have been removed
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b)	have been remediated in compliance with duction equipment and junk have been removed eved. (Poured onsite concrete bases do not have
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules.	have been remediated in compliance with duction equipment and junk have been removed eved. (Poured onsite concrete bases do not have
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location (s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to self-	have been remediated in compliance with fluction equipment and junk have been removed eved. (Poured onsite concrete bases do not have NMAC. All fluids have been removed from hedule an inspection. If more than one
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location (s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines.	have been remediated in compliance with fluction equipment and junk have been removed eved. (Poured onsite concrete bases do not have NMAC. All fluids have been removed from hedule an inspection. If more than one
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location (s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to self-	have been remediated in compliance with fluction equipment and junk have been removed eved. (Poured onsite concrete bases do not have NMAC. All fluids have been removed from hedule an inspection. If more than one
Anchors, dead men, tie downs and risers have been cut off at least two feet below groud If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to sel inspection has to be made to a P&A location because it does not meet the criteria above, a SIGNATURE TITLE TROUBLES E-MAIL:	NMAC. All fluids have been removed from ledule an inspection. If more than one benalty may be assessed.
Anchors, dead men, tie downs and risers have been cut off at least two feet below groud If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to soluspection has to be made to a P&A location because it does not meet the criteria above, a possible of the content of the content and the criteria above, a possible of the criteria above of the cri	NMAC. All fluids have been removed from sedule an inspection. If more than one benalty may be assessed. DATE DATE On the description of the des