Form 3400-5 (August 2007)

DEPARTMENT OF THE INTERIOR B 19 2009 BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

FORM A	PP	RO	VED
OMB No	10	04-	-013
Expirer	ol.	3.1	201

5 Lease Serial No NMNM033775

Do not use this form for proposals to drill or to re-enter an

6 If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160	0-3 (APD) for such propo	sals.			
SUBMIT IN TRIPLICATE – Other instructions on page 2		7 If Unit	7 If Unit of CA/Agreement, Name and/or No NMNM70993X		
i Type of Well					
Oil Well Gas Well Other Injection		8 Well Na	8 Well Name and No North Benson Queen Unit #14		
2 Name of Operator Arena Resources Inc		9 API We			
3a Address	3b. Phone No (include area	a code) 10. Field a	10. Field and Pool or Exploratory Area		
2130 W Bender Hobbs, NM 88240	575-738-1739	. 1	enson Queen Grayburg North		
4 Location of Well (Footage, Sec., T.R.M., or Survey Desc	cription)	. II Countr	y or Parish, State		
Sec. 28 T18S, R30 E 1980' FSL 660' FWL		·	Eddy		
.12 CHECK THE APPROPRIA	ATE BOX(ES) TO INDICATE NAT	URE OF NOTICE, REPOR	T OR OTHER DATA		
TYPE OF SUBMISSION	^	TYPE OF ACTION			
✓ Notice of Intent	Deepen .	Production (Start	/Resume) Water Shut-Off		
Alter Casing	Fracture Treat	Reclamation	Well integrity		
Subsequent Report Casing Repair	r New Construction	Recomplete	Other		
Change Plans	Plug and Abandon	Temporarily Aba	ndon		
Final Abandonment Notice Convert to Inj	ection Plug Back	Water Disposal			
3. Tag T.O.C. Displace hole with salt gel mud. Pull up 4. Tag T.O.C. Pull up hole and spot 25 sk plug ± 675'-5. Tag T.O.C. POOH. RIH & perforate csg @ 60', RIH 5. Cut off wellhead and install dry hole marker  SEE ATTACI	w/ top of salt) w/ tog to 60' & spot plug 60' to su	Tana	APPROVED FEB 1 7 2009		
CONDITIONS OF APPROVAL					
•	,	-	JAMES A. AMOS SUPERVISOR-EPS		
14 I hereby certify that the foregoing is true and correct Name	(Printed Typed)				
Colleen Robinson	Title Com	oliance Analyst		•	
Signature alum skins en	Date 02/04	I/2009	1	, , ,	
THIS SP.	ACE FOR FEDERAL OR	STATE OFFICE US	Ē ,		
Approved by		,			
	Tutla		Date	•	
Conditions of approval, if any, are attached. Approval of this not that the applicant holds legal or equitable title to those rights in the entitle the applicant to conduct operations thereon.			LDAIC		
Title 18 U S C Section 1001 and Title 43 U S C Section 1212, m	nake it a crime for any person knowing	v and willfully to make to an	v department or agency of the United Sta	tes any false.	

WELL NAME FIELD

NORTH BENSON QUEEN UNIT # 14 NORTH BENSON QUEEN-GRAYBURG

KB ~3434 ° DF 3433

JNTY, STATE

EDDY COUNTY, NEW MEXICO

GL 34231

CSG LEAK @ 140

520

COMPL. DATE 11/10/63

CASING

REMARKS: 3 UNSUCCESSELL ATTEMPTS

TO SOF LEAK @ 140'

\* PRIOR TO PEA

CASING SIZE 4 1/2", 9-5 SET @ 3250 PERFORATIONS:

1 JSPF 26391 26461

28501

2862

3146!

3156'

3182'

TD 3250' HOLE SIZE 6 1/4" PBTD 3222'

DATE PREPARED: 2-6-09 DC

3433 DF FIELD NORTH BENSON QUEEN-GRAYBURG JNTY, STATE EDDY COUNTY, NEW MEXICO GLCOMPL. DATE 11/10/63 PERF @ 60' PLUG 60 - SURFACE CASING 520 \_\_ 25 SX PLUG 675'-300' REMARKS: HOLE FULL SALT GEL MID 25 SX PLUG 1525 -1150 (TOP YATES / BASE SACT). PROPOSED PERFORATIONS: 1 JSPF 2639 26461 T.O.C. 2215 28621 1 1 Z 3146! 3156' 25 SX PLUG 3182' CASING SIZE SET 0 3250 ٠ ۷ CIBP @ 2589 TD 3250' HOLE SIZE 6 1/4" PBTD 3222'

NORTH BENSON QUEEN UNIT # 14

KB 3434

DATE PREPARED: 2-6-09 DC

WELL NAME

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.