

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

FEB 24 2009

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1 Type of Well
☐ Oil Well ☒ Gas Well ☐ Other2 Name of Operator
BOPCO, L. P.3a Address
P. O. BOX 2760 Midland TX 797053b Phone No. (include area code)
(432)683-22774 Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980' FSL, 1980' FEL, SEC 35, T21S, R28E

5 Lease Serial No.

LC067144

6. If Indian, Allottee or Tribe Name

7 If Unit or CA/Agreement, Name and/or No

8 Well Name and No

BIG EDDY #41

9. API Well No

30-015-21325

10. Field and Pool, or Exploratory Area

INDIAN FLATS (ATOKA)

11. County or Parish, State

EDDY

NM

12 CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Test Bone
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Spring & Dela-
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	ware

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BEPKO, L. P. respectfully wishes to report the Plug and Abandonment of the subject wellbore as follows:

12/17-20/2008: MIRU Lucky Well Service & Black Warrior WL & attempt to set CIBP @ 10170' to find previously set Baker CR @ 10164'. POOH w/ CIBP, PU & RIH w/ 4 -3/4" Mill tooth bit. Drill out CR to have fall free.

12/23/2008: RU BWWC & RIH w/ 10K CIBP & Set @ 10905'. PU 2-2/8" csg gun & perf @ 9715 w/ 4 total shots across top of Wolfcamp. Bail 35' of Class H cmt on top of CIBP, TOC @ 10870'.

12/24/2008: RIH w/ 314 jts 2-3/8" tbg & 5-1/2" Baker retriev. pkr & set @ 9334'. Could not pump into perfs. Carlsbad BLM instructed to spot minimum 200' cmt w/ 50' below bottom perf. Move pkr To 9778' & pump 35 sxs Class H cmt.

12/25/2008: RIH & tagged TOC @ 9273'. Log wellbore from 7650-2650'. PU 5-1/2" CIBP & set @ 7450'.

12/30/2008: RIH w/ 2-3/8" tubing & land EOT @ 7209'. Pump 100 gals 15% HCL across future perfs.

12/31/2008: Perf Bone Spring @ 7160-82' w/ 46 shots. Acidize w/ 3500 gals HCL dropping 75 1.2 SG ball sealers.

01/01-03/2009: Open to tank & bled down & swabbed wellbore until no fluid was recovered.

01/06/2009: RIH w/ 5-1/2" 10K CIBP & set @ 7100'. Pu 3-3/8" csg gun & perf Bone Spring @ 6300'. Dump bailed 35' class H cmt on top of CIBP. RIH w/ 2-3/8" retrievomatic pkr & land @ 7038'. Spot 17.5 bbls salt gel mud to 6300'. Re-land pkr @ 6010' & pump 50 sxs class C. cmt. POOH w/ tbg & LD pkr.

tbg to 2879'. Pump 25 sxs Class C cmt. WOC. Tag TOC @ 2733'. SEE ATTACHMENT

14 I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Ann Moore

Title Sr. Regulatory Clerk

Date 02/10/2009

Approved as to plugging of the well bore.
Liability under bond is retained until
Surface restoration is completed.

Signature

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

APPROVED

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Title

Office

Date

FEB 21 2009

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

JAMES A. AMOS
SUPERVISOR-EPS

(Instructions on page 2)

ATTACHMENT TO BIG EDDY #41 P & A 3160-5

01/17/2009: Set CIBP @ 3475'. Perf 4 sqz. Holes @ 2845' & dump bail 36' of Class C cmt on top of CIBP. RIH w/ 2-3/8" tbg. & land tbg. @ 3436'. Pump 14 bbls salt gel mud. PUH w/ tbg to 2879'. Pump 25 sxs class C Cmt. WOC. Tag TOC @ 2733'.

01/20/2009: RU weatherford WL & RIH w/ 2-2/8" csg gun & perf 4spf @ 2385'. Re-tag TOC @ 2706'. POOH w/ WL. RIH w 86 jts 2-3/8" tbg. & pump 7 bbls salt water gel to 2385'. POOH w/ 10 jts tbg to land @ 2391' & spot 25 sxs class C cmt. POOH w/ 12 jts. of tbg. to land @ 2133' & squeeze 1/2 bbl cmt w/ 2000 psi. POOH w/ tbg. PU Csg gun & RIH to tag TOC @ 2102'. Perf 4 squeeze holes @ 490'. POOH w/ tools. RIH w/ 67 jts 2-3/8" tbg to land @ 2095'. Pump 40 bbls salt water gel to 490'. POOH & LD 51 jts tbg to land @ 508'. Pump 45 sxs Class C cmt. POOH w/ 6 jts to land @ 321'. Displace 2.5 bbls cmt to perfs. POOH & SD. BLM's Legion Brumley witnessed daily activities.

01/21/2009: PU 3-3/8" csg gun & RIH to TOC @ 290'. PU & perf 4 squeeze holes @ 100'. POOH w/ tools & RD Weatherford WL. RIH w/ 9 jts 2-3/8" prod. Tbg to re-tag cmt @ 290'. RU Rising Star & pump 1 bbl FW followed by 8 sxs Class C Cmt. spotted to 204', POOH & LD tbg. RU RS to 5-1/2" csg & pump 25 sxs Class C cmt circulated to surface. RD Rising Star. Dig out cellar & cut off wellhead. Install dry hole marker. Haul tubing to Carlsbad & backdrag location. Final report of daily activities witnessed by BLM rep Legion Brumley.