

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S. St Francis Dr, Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAR 12 2009

Form C-103
June 19, 2008

AM

WELL API NO. 30-015-25141
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. SWD 666
7. Lease Name or Unit Agreement Name Belco
8. Well Number 1
9. OGRID Number 303946
10. Pool name or Wildcat 96100-Delaware
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD

2. Name of Operator
Basic Energy Services LP

3. Address of Operator
PO Box 10460, Midland, TX 79702

4. Well Location
Unit Letter E : 2200 feet from the N line and 660 feet from the W line
Section 20 Township 23 Range 28 NMPM County Eddy

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SWD 666

Plan to add additional perforations within the Delaware

- 1) Pull equipment, clean out casing
- 2) Add additional perforations at approximately 3950 to 4250
- 3) Acidize perfs
- 4) Run in hole with IPC tubing and pkr, set at approximately 3850
- 5) Perform pressure test as UIC requires
- 6) Notify OCD before starting workover and before testing to witness
- 7) File subsequent report of work

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve Prather TITLE Area Manager DATE 3/11/09

Type or print name Steve Prather E-mail address Steve.Prather@basicenergy PHONE: 575-390-1435
For State Use Only energyservices.com

APPROVED BY: Jacqui Prather TITLE Geologist DATE 3/12/09

Conditions of Approval (if any):