' Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

&E - CFO	FORM APPRO
	OMB No 1004

VED 1-0135 Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		5. Lease Serial No. NM 4/6.5.5  6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side		7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well Oil Well Gas Well Other		8 Well Name and No.  Scott Fed # 1			
2. Name of Operator  NMOCO FOR CFO Management  3a. Address  3b. Phone No. (include area code)		9. API Well No. 30-015-25437			
4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)		10. Field and Pool, or Exploratory Area			
610'FSL 660'FEL 12,-+175-27E		EDDY CO, NM			
	RIATE BOX(ES) TO INI			PORT, OR OTHER	DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction X Plug and Abandon Plug Back	Reclamation Recomplete Temporarily Water Dispo	Abandon sal	Water Shut-Off  Well Integrity  Other
13. Describe Proposed of Completed Operation (cl If the proposal is to deepen directionally or reco Attach the Bond under which the work will be following completion of the involved operations testing has been completed. Final Abandonm determined that the site is ready for final inspect	omplete horizontally, give subsurface to performed or provide the Bond No of If the operation results in a multiple	locations and measured and true of the file with BLM/BIA. Required so the completion or recompletion in a	vertical depths of all pe subsequent reports sha i new interval, a Form (	ertinent markers and zones. Ill be filed within 30 days 3160-4 shall be filed once	FD F∩R
testing has been completed. Final Abandonm determined that the site is ready for final inspect of the state of the site is ready for final inspect of the site is ready for fi	1150 W/ sx from 3 hole Marker	2554 on 44! To Sur	tece	CONDITIONS	OF APPROVA
& Cuttott	well hear	<b>J</b>	groun	d level	fill
annilus.	from 50'-	· Surf.			
Steel Pito h	Ill be Use	L			•
14. Thereby certify that the foregoing is true  Name (Printed/Typed)  Mar L Hos Kins		Title Caer	t for	NMOCD	
Signature Mak De	ol	Date 3/3	olog		OVED
	THIS SPACE FOR	PERENAL OR STATE (	DEELCE LISE		

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office JAMES A. AMOS

2 2009

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willbully to make to any department of agency of the United

Title

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Operator: C & D Management Company
Surface Lease: NM41655

Horz Linked Lse No(s): N.A.
Unit or CA No: N.A.


KB@: 3507

GL@: 3501

Well: Scott Federal #1 API: 3001525437

@ Srfce: T17S-R27E, Sec 12, 660FSL & 660FEL

@ M TD: N.A.





## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 38220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.