

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

APR - 8 2009

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-30907
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-5512
7. Lease Name or Unit Agreement Name NO BLUFF STATE COM
8. Well Number #1
9. OGRID Number 255333
10. Pool name or Wildcat Logan Draw, Wolfcamp (96960) /
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3589' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

LIME ROCK RESOURCES A, L.P.

3. Address of Operator

c/o Mike Pippin LLC, 3104 N. Sullivan, Farmington, NM 87401

4. Well Location

Unit Letter D : 660 feet from the NORTH line and 860 feet from the WEST line
Section 36 Township 17-S Range 27-E NMPM EDDY County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Recomplete into Wolfcamp ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Lime Rock Resources plans to recomplete this Illinois Camp; Morrow, North Gas Pool (78890) well into the Logan Draw, Wolfcamp pool (96960) as follows:

MIRUSU. TOH w/tbg. Set CIBP @ 9600' & top w/10' of cmt. PT 5-1/2" csg to 3000 psi for 30 min. Perf Logan Draw, Wolfcamp @ about 6936'-54' & 7072'-78'. Set 5-1/2" pkr @ ~6880' on 2-7/8" tbg. Break down new Wolfcamp perfs w/about 4000 gal 15% NEFE acid. Treat perfs w/about 30,000 gal 20% hot acid & about 40,000 gal hot 40# linear gel followed by about 3500 gal 15% cool down acid. Swab well. TOH w/tbg & pkr. Land 2-7/8" tbg @ about 7125', run pump & rods & initiate pumping load water.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Pippin TITLE Petroleum Engineer - Agent DATE 4/7/09

Type or print name Mike Pippin E-mail address: mike@pippinllc.com PHONE: 505-327-4573

For State Use Only

APPROVED BY: [Signature] TITLE Geologist DATE 4/9/09

Conditions of Approval (if any):