

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA
APR 15 2009

FORM APPROVED
OMB No 1004-0137
Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No
NM-100558

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE – Other instructions on page 2.

1. Type of Well

☒ Oil Well

☐ Gas Well

☐ Other

2. Name of Operator

RKI EXPLORATION & PRODUCTION, LLC

3a. Address

3817 NW EXPRESSWAY, SUITE 950
OKLAHOMA CITY, OK 73112

3b. Phone No. (include area code)

405-949-2221

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.
RDX 9-1

9. API Well No
30-015-36211

10. Field and Pool or Exploratory Area
BRUSHY DRAW DELAWARE EAST

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990 FSL, 990 FEL, SEC 9, T-26S, R-30E

11. Country or Parish, State
EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☒ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other _____
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☒ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

RKI EXPLORATION & PRODUCTION, LLC REQUESTS PERMISSION TO DISPOSE OF PRODUCED WATER VIA A 3" POLY LINE TO THE CRW DISPOSAL SYSTEM.

THE CRW SWD NM-55685 ROSS DRAW COM #1 IS LOCATED AT THE NE/NW 1/4 OF SEC. 33, T-26S, R-30E IN EDDY COUNTY, NM

THIS WELL PRODUCES BETWEEN 150 - 180 BBLS OF WATER PER DAY.

Accepted for record
NMOCB
BT

ACCEPTED FOR RECORD

APR 13 2009
/s/ JD Whitlock Jr

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

GENE SIMER

Title PRODUCTION SUPERINTENDENT

Signature

Gene Simer

Date 03/30/2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)