

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

FFR 25 2009

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NSB0803137626

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Fairway Resources Operating	Contact	Matt Eagleston
Address	538 Silicon Drive, Ste. 101, Southlake, Texas 76092	Telephone No	(817) 416-1946
Facility Name	Midnight Matador "A" #4	Facility Type	Oil Well

Surface Owner	US - BLM	Mineral Owner	US - BLM	Lease No.	NM LC-055561
---------------	----------	---------------	----------	-----------	--------------

3001501231

LOCATION OF RELEASE

Unit Letter "B"	Section 35	Township 17S	Range 27E	Feet from the 990'	North/South Line North	Feet from the 1,650	East/West Line East	County Eddy
--------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32° 47' 42.4" North

Longitude 104° 14' 44.9" West

NATURE OF RELEASE



Type of Release	Crude Oil & Produced Water	Volume of Release	Unknown	Volume Recovered	0 (Zero)
Source of Release	Wellhead	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	1/16/2008 0800 MST
Was Immediate Notice Given?	Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required <input checked="" type="checkbox"/>	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken. A BLM inspection on January 16, 2008 found evidence of a release and soil impact on the north side of the wellhead area. No free liquids were observed or recovered onsite.

Describe Area Affected and Cleanup Action Taken. A soil investigation was completed and analytical results indicated soil impact was not present below the gypsum cap. Excavation of the impacted soil was staged and soil samples were collected and submitted to the laboratory for analysis between excavation activities. Approximately 1,110 cubic yards of impacted soil was transported to Lea Land Landfill (Permit #NM-01-0035) for disposal. With NMOCD Artesia Office approval the excavation was backfilled with locally purchased native soil. A Remediation Summary and Site Closure Request dated January 2009 was submitted to the NMOCD Artesia Office and contains additional details and documentation not contained in this document.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Matt Eagleston	Approved by District Supervisor: 	
Title: President and CEO	Approval Date: 4-28-09	Expiration Date: N/A
E-mail Address: meagleston@fairwayresources.com	Conditions of Approval: N/A	2RP-0124 N/A
Date:	Phone: (817) 416-1946	