Well X Oil Well

P.O. Box 2760 Midland TX 79702

2 Name of Operator BOPCO, L.P. 3a. Address

## UNITEDSTATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

CHMDDA	MOTICES	AND	DEDODTS	ON WELLS
SUNDRY	MULICES	AND	REPURIS	ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

Other

Gas Well

4. Location of Well (Footage, Sec , T., R., M , or Survey Description) UL K, SEC 19, T20S, T31E, 1656' FSL, 1972' FWL

18	2009	Expires March 31, 2007
•	5. Lease So	erial No
	NMLC0	70220
	6 If Indian	, Allottee or Tribe Name
	7 If Unit	or CA/Agreement, Name and/or No.
	NMNM	38294H
	8 Well Na	ime and No.
	Big Edd	ly Unit #10
	9. API We	il No
	30-015	-10785
	10 Field a	and Pool, or Exploratory Area
	Big Edd	ly (Strawn)
	11 Count	y or Parish, State
	Eddy	
	NM	
, R	EPORT, O	R OTHER DATA
. ,		
(Sta	rt/Resume)	Water Shut-Off
n		Well Integrity

12. CHECK APPROPRIATE BOX(ES)TO INDICATE NATURE OF NOTICE TYPE OF SUBMISSION TYPE OF ACTION ∆ Acıdıze Deepen Production X Notice of Intent Alter Casing Reclamatio X OtherExtend P & A ☐ Casing Repair \_\_ New Construction Recomplete Subsequent Report X Plug and Abandon □ Change Plans ☐ Temporarily Abandon NOI J Final Abandonment Notice Convert to Injection PlugBack Water Disposal

3b Phone No (include area code)

(432)683-2277

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BOPCO, L.P. respectfully requests the extension of the approved P & A procedure, for the subject wellbore, that was granted on February 28, 2009. BOPCO, L.P. would like the additional time to re-evaluate the potential of the wellbore before abandonment. The current P & A procedure expires on May 28, 2009. BOPCO, L.P. will have the wellbore returned to usefulness or P & A'd within 90 days if an extension is granted. Please find the attached approved P & A procedure.

APPROVED

MAY 1 6 2009

JAMES A. AMOS
SUPERVISOR-EPS

			JAMES A. AMOS SUPERVISOR-EPS	
Good T:11 8-21-09		\		
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)				
Valerie Truax	Title	Regulatory Admin Ass	sistant	
Signature Molecue Truck	Date	05/07/2009		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by		Title	Date	
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon		Office		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction				

(Instructions on page 2)

8/3/19/05

Form 3160-5 (April2004)

## UNITEDSTATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OPERAT	OR'S COMY No. 1004-0137 Expires: March 31, 2007	W
	5. Lease Serial No.	

<ol><li>Lease Serial No.</li></ol>		-	
NMLC070220			
6. If Indian, Allottee or	Tribe N	ame	

SUNDRY	NOTICES AND REPORTS OF	N WELLS	NIVILCU/UZZU
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No. NMNM68294H
I. Type of Well  X Oil Well  Gas Well  Other			8. Well Name and No.
2. Name of Operator			Big Eddy Unit #10
BOPCO, L.P.  3a. Address  3b. PhoneNo. (include area code)		9. API Well No. 30-015-10785	
P.O. Box 2760 Midland T	X 79702 (432)6	583-2277	10. Field and Pool, or Exploratory Area Big Eddy (Strawn)
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  UL K, SEC 19, T20S, T2/E, 1656' FSL, 1972' FWL			11. County or Parish, State Eddy NM
12. CHECK AI	PPROPRIATE BOX(ES)TO INDICATE	NATURE OF NOTION	CE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTIO	N
X Notice of Intent  ☐ Subsequent Report ☐ Final Abandonment Notice	Acidize Deepen AlterCasing FractureTi Casing Repair New Cons Change Plans X Plug and A Convert to Injection Plug Back	eat Reclama truction Recomp bandon Tempora	lete Other
testing has been completed. Findetermined that the site is read BOPCO, L.P. respectful.  1. MIRU PU & plugging 2-3/8" tbg. 2. Test 2-3/8" x 5-1/2" a 3. POOH 51 ft of 2-3/8" 4. Spot 20 SX Class H 6. Spot 65 SX Class H 6. Spot 65 SX Class Cla	nal Abandonment Notices shall be filed only after y for final inspection.)  ly requests permission to plug and equipment. Set open top steel pit nnulus to check tubing integrity. Cotubing.  Comt on CIBP. 25 \$× \$\times\$ (0340' - 10560'.)  3675' - 4000' PERF SQZ. \$\times\$ 0 \$\times\$ (3675' - 3275' TAG.)  2525' - 3275' TAG.	all requirements, including displayed abandon the substitution of	WH & NU 3,000 psi manual BOP for
12. Spot 40 SX Class C	965' - 1075'. TAG		e steel tank and haul all fluids.
14. I hereby certify that the fore Name (Printed/Typed)	egoing is true and correct	1	
Valerie Truax		Title Regulator	y Admin Assistant
Signature Milen	: Luck	Date 02/20/200	9 ACCEPTED FOR RECORD
	THIS SPACE FOR FEDERAL	OR STATE OF	FICE USE
certify that the applicant holds leg which would entitle the applican		lease Office	willfully to make to the partition.  ARISBAD FIELD OFFICE
States any false, fictitious or frau	idulent statements or representations as to any	matter within its jurisdi	CARLSBAD FIELD OFFICE

(Instructions on page 2)

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement.</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds)
- 7 <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you