Submit 3 Copies To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resources		JUN - 1 2009	Form C-103 / M June 19, 2008
1625 N French Dr , Hobbs, NM 88240	- ;		WELL API NO.	
District II 1301 W. Grand Ave, Artesia, NM 88210			5. Indicate Type of Le	
District III 1000 Rio Brazos Rd, Aztec, NM 87410	1220 South St. Francis Dr.		STATE 🛛	FEE
District IV	Santa, Fe, NM 87505		6. State Oil & Gas Lea	ise No.
1220 S St Francis Dr , Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR—USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name CTA State Com	
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other			8. Well Number	
2. Name of Operator			9. OGRID Number	
Marbob Energy Corporation 3. Address of Operator			14049 10. Pool name or Wildcat	
PO Box 227, Artesia, NM 88211-0227			Benson; Strawn (Consolidated)	
4. Well Location				
Unit Letter C:	660 feet from the No	rth line and	1980 feet from the	West line
Section 32		nge 30E	NMPM Eddy	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3419' GL				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A				ND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB	
DOWNHOLE COMMINGLE				
OTHER:			ecompletion	\boxtimes
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
Recompleted in the Strawn	zone as follows:			
AND				
4/14/09 - MIRU. POOH w/ rods & pump. 4/15/09 - POOH w/ tbg. Set CICR @ 11367'.				
4/16/09 – Sqz Morrow perfs @ 11427' – 11492' w/ 100 sx cmt.				
4/17/09 – Drill out cmt & CICR @ 11367'.				
4/18/09 – Drill out cmt to CIBP @ 11620'. 4/21/09 – Drill out CIBP @ 11620'. Drill out cmt to 11700'. Fall thru cmt. Tag @ 11890'. Circ cln.				
4/22/09 – Re-perf the Lower Morrow @ 11670' – 11700' (93 shots).				
4/23/09 – Acdz w/ 1500 gal NE Fe 7 ½% HCl Morrow acid.				
4/28/09 - Set CIBP + 35' cmt @ 11400'. Zone abandoned - Morrow. Perf the Strawn @ 10544' - 10580' (27 shots) 4/29/09 - Set pkr @ 10494'. Acdz Strawn w/ 3040 gal NE Fe 15% HCl acid. R1H w/ 329 jts 2 3/8' L80 tbg. Set @ 10506'.				
	ng interval: Strawn @ 10544' – 10		m w/ 329 jis 2 3/6 - Lou ii	og. Set @ 10300.
	The state of the s			
Spud Date:	Rig Release Da	ate:		
1				and the second of the second o
I hereby cotify that the information	above is true and complete to the h	act of my knowledge	ro and haliaf	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE	TITLE_Pr	oduction Manager_	DATE	5/27/09
Type or print name Diana . B For State Use Only	riggs E-mail address: _pro	oduction@marbob.c	com PHONE: _(575	748-3303_
APPROVED BY: Conditions of Approval (if any):	TITLE (zeologist	DATE	61213009

--