OCD-ARTESIA

STEPTER MINERAL GOOD BELL TOUR

R	M
---	---

(April 2004) UNITED STATE DEPARTMENT OF THI BUREAU OF LAND MAI	EINTERIOR AUG 25 200				
SUNDRY NOTICES AND RE		5 Lease Serial No LC 029393C			
Do not use this form for proposals abandoned well. Use Form 3160-3	to drill or to re-enter an	6 If Indian. Allottee or Tribe Name			
SUBMIT IN TRIPLICATE- Other inst	tructions on reverse side.	7 If Unit or CA/Agreement Name and/or No			
1 Type of Well Gas Well Other		8 Well Name and No			
2 Name of Operator COG Operating		V.S. Unit 108			
3a Address 550 W. Texas Ste 1300 Midland, TX 79701	3b Phone No (include area code) 432-686-3021	30-015-05573 10 Field and Pool, or Exploratory Area			
4 Location of Well (Footage, Sec., T., R. M., or Survey Description)					
1980' FNL & 660' FWL, Section 16, T-18-S. R-31-E		11 County or Parish, State			
		Eddy, New Mexico			
12. CHECK APPROPRIATE BOX(ES) TO	DINDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION				
Acidize Alter Casing Subsequent Report Final Abandonment Notice Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Fracture Treat Reclamation New Construction Recomplete	ecomplete Other			
13 Describe Proposed or Completed Operation (clearly state all pert If the proposal is to deepen directionally or recomplete horizonta Attach the Bond under which the work will be performed or prov following completion of the involved operations. If the operation testing has been completed. Final Abandonment Notices shall be determined that the site is ready for final inspection.)	Ily, give subsurface locations and measured and trivide the Bond No on file with BLM/BIA Require results in a multiple completion or recompletion	ue vertical depths of all pertinent markers and zones red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once			
7/23/2009 Set CIBP @ 3000' 7/27/2009 Spot 25sxs cmt @ 3000' 7/27/2009 Perf @ 2450' Pressure up to 1500 PSI Held (0 7/27/2009 Spot 30sxs cmt @ 2500' WOC tag plug @ 23: 7/28/2009 Perf @ 1800' Sqz 50sxs cmt @ 1800' WOC no 7/29/2009 Sqz 100sxs cmt WOC tag plug @ 1324' 7/30/2009 Perf @ 900' Sqz 60sxs cmt @ 900' WOC tag cmt 7/31/2009 Install Dry Hole Marker	22' o tag. Re squeeze 50sxs cmt @ 1800' WOC t	ag plug @ 1487' Pressure test did not Hold			
	Liabil	ted as to plugging of the well bore. ity under bond is retained until e restoration is completed.			

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)						
Larry Winn	Title Area Manager, P&A Basic Energy Services 432,530-0907					
Signature LLL	Date	08A6269	EPTED FOF	REC(JRD	
THIS SPACE FOR FEDERAL	OR STATE OFFICE	USE			_	
Approved by	Title		DatAUG 2 1	2009	==	
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon	ease Office		flm o		*****	
Which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to anymattee.	person knowingly and willfully within its jurisdiction.	y to make to	JREAU OF LAND M /CARLSBAD FIELI	ANAGE ME D'OFFICE	ied ied	
(Instructions on page 2)						