


Submit One Copy To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-103
March 18, 2009

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-63389																
1. Type of Well: <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other Dry & Abandoned		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>																
2. Name of Operator EXCO Resources, Inc.		6. State Oil & Gas Lease No.																
3. Address of Operator 12377 Merit Drive, Ste. 1700, Dallas, TX 75251		7. Lease Name or Unit Agreement Name Rose Federal																
4. Well Location Unit Letter E : 1980 feet from the North line and 660 feet from the West line Section 21 Township 05S Range 25E NMPM NM County Chaves		8. Well Number 18																
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3803' GR		9. OGRID Number 190963																
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data																		
<table border="0"><tr><td>NOTICE OF INTENTION TO:</td><td>SUBSEQUENT REPORT OF:</td></tr><tr><td>PERFORM REMEDIAL WORK <input type="checkbox"/></td><td>REMEDIAL WORK <input type="checkbox"/></td></tr><tr><td>TEMPORARILY ABANDON <input type="checkbox"/></td><td>ALTERING CASING <input type="checkbox"/></td></tr><tr><td>PULL OR ALTER CASING <input type="checkbox"/></td><td>COMMENCE DRILLING OPNS. <input type="checkbox"/></td></tr><tr><td>PLUG AND ABANDON <input type="checkbox"/></td><td>P AND A <input type="checkbox"/></td></tr><tr><td>CHANGE PLANS <input type="checkbox"/></td><td>CASING/CEMENT JOB <input type="checkbox"/></td></tr><tr><td>MULTIPLE COMPL <input type="checkbox"/></td><td></td></tr><tr><td>OTHER: <input type="checkbox"/></td><td><input checked="" type="checkbox"/> Location is ready for OCD Inspection after P&A</td></tr></table>			NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	P AND A <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>		OTHER: <input type="checkbox"/>	<input checked="" type="checkbox"/> Location is ready for OCD Inspection after P&A
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:																	
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>																	
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>																	
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>																	
PLUG AND ABANDON <input type="checkbox"/>	P AND A <input type="checkbox"/>																	
CHANGE PLANS <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>																	
MULTIPLE COMPL <input type="checkbox"/>																		
OTHER: <input type="checkbox"/>	<input checked="" type="checkbox"/> Location is ready for OCD Inspection after P&A																	
<input checked="" type="checkbox"/> All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. <input checked="" type="checkbox"/> Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. <input checked="" type="checkbox"/> A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the																		

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- ☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- ☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- ☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- ☒ All other environmental concerns have been addressed as per OCD rules.
- ☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Sharon Figueroa TITLE Production Administrator DATE 10/28/2009

TYPE OR PRINT NAME Sharon Figueroa E-MAIL: sfigueroa@excoresources.com PHONE: 214-368-2084

For State Use Only

APPROVED BY: [Signature] TITLE OK To Release DATE 11/16/09

Conditions of Approval (if any):