artesia

Form 3160-5 (April 2004)

Subsequent Report

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No 1004-0137 Expires March 31, 2007

THINOCD 5 Lease Serial No LC-029435-A

SUNDRY NOTICES AND REPORTS ON WELLS

If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No-SUBMIT IN TRIPLICATE- Other instructions on reverse side. Öil Well 🗆 🗇 Gas Well□□ 8 . Well Name and No. J. L. Keel A #3 2 Name of Operator Merit Energy Company API Well No 30-015-05091 3a Address 3b Phone No (include area code) 13727 Noel Rd. Suite 500 Dallas, Texas 75240 972-628-1569 10 Field and Pool, or Exploratory Area 4 Location of Well (Footage, Sec., T., R., M., or Survey Description) Grayburg-Jackson 11 County or Parish, State 330' FSL & 1650' FWL Sec. 7-T17S-R31E Eddy Co., New Mexico 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Acidize Production (Start/Resume) Water Shut-Off Deepen ✓ Notice of Intent ✓ Well Integrity Alter Casing Fracture Treat Reclamation Casing Repair New Construction Recomplete

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug and Abandon

Plug Back

Temporarily Abandon

Water Disposal

MIRU PU. ND WH. NU BOPE. Unseat injection pkr. POOH w/pkr. & tbg. standing back. PU. RIH w/fullbore pkr. Set +/- 50' above perforations. Test csg. PU. RIH w/injection pkr. on injection tbg. string testing in. Replace any bad jts. of tbg. Set injection pkr. +/- 50' above perforations. ND BOPE. NU WH. RDMO PU. Run State Witnessed MIT. Return well to injection.

workdone grior to Altroval

RT-AMOTA Works

☐ Convert to Injection

ACCEPTED FOR RECORD

OCT 2 7 2009 /s/ JD Whitlock Jr

BUREAU OF LAND MANAGEMENT CARLSBAD FIFLD OFFICE

1170		-				
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)	, !	,	,			
Lynne Moon	Title	Title Regulatory Manager				
Signature Line Moon	Date	2	٠,	10/16/2009		
THIS SPACE FOR FEDE	RAL OF	STAT	E OFFI	CE USE	,	
Approved by	. *	Title		,	Date ·	
Conditions of approval, if any, are attached Approval of this notice does not certify that the applicant holds legal or equitable title to those rights in the sul which would entitle the applicant to conduct operations thereon.		Office				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime	for any perso	n knowingl	y and will	ully to make to	any department of	or agency of the United

(Instructions on page 2)

