1 orm 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED

	OMB N	0 10	04-	()
	Expues	July	31,	21
Lease Seria	l No			_

SUNDRY	NOTICES	AND RE	PORTS (	ON WELLS
30	thin form for	proposale	to drill or	to re-enter a

SUNDRY NOTICES AND REPORTS ON WELLS			NM	NM101108	
Do not use this form for proposals to drill or to re-enter an			If Indian, Allottee.	THECEIVED	
abandoned well. Use Form 3160-3 (APD) for such proposals.			If I but on CA. Aut	econent Notes and/out No.	
SUBMIT IN TRIPLICATE - Other Instru	ictions on page 2		I Count Of City The	ement NaDEC 101 6 2009	
Oth Well Gas Well X Other SWD		8	Well Name and N	I MMUCD ARTEST	
2 Name of Operator				8 Federal SWD#1	
Marbob Energy Corporation	T. N. N.		API Well No		
3a Address P.O. Box 227	3b Phone No (inch	de area code)	30-	015-31675	
Artesia, NM 88211-0227	575-748-3303		10 Field and Pool, or Exploratory Area		
4 Location of Well (Footage, Sec., T. R., M., or Survey Description)  Lat.			SWD; Delaware		
660' FNL & 330' FEL, Unit A (NENE)	Long	11	County or Parish		
Sec 8-T26S-R29E	Long.		Eddy	NM	
12. CHECK APPROPRIATE BOX(S) TO INDICA	ATE NATURE OF	NOTICE, REPORT,	OR OTHER D	ATA	
TYPE OF SUBMISSION	TY	PE OF ACTION			
Notice of Intent Acidize	Deepen	Production ( Start/	Resume)	Water Shut-off	
Altering Casing	Fracture Treat	Reclamation		Well Integrity	
X Subsequent Report Casing Repair	New Construction	Recomplete	Σ	( Other	
Change Plans	Plug and abandon	Temporarily Aban	don R	e-Entry Operations	
Final Abandonment Notice Convert to Injection	Plug back	Water Disposal			
testing has been completed. Final Abandonment Notice shall be file determined that the site is ready for final inspection.)  10/6/09 MIRU WSU. NU BOP. Unload & tally 2		_			
10/7/09 to 10/13/09 Drill cement & plugs to 4428'	=		start driffing c	in surface plug.	
10/14/09 Pressure casing to 940#. BLM witnessed			sing to 900#	Lost 100#	
Failed both CIT's. Run CBL from PBTD to 100'.	a. Bost room in o	mino. Trossaro ca	, mg to 200m.	Lost room.	
10/15/09 Tag @ 4428'. PU swivel & start drilling	. Tag CIBP @ 48	38'. Drilled out.	ag plug @ 5	186'. Set packer @	
5138'. Test cement plug @ 5186' to 2000#. Good			<del>-</del>		
10/16/09 TIH w/retainer & set @ 4850'. Pumped	, -		=	~	
sx Premium Plus. TOOH.			Ü	•	
10/19/09 Pressure test casing. Original squeeze ho	oles @ 1007' & 2	950' leaking.			
10/20/09 Set retainer @ 2755'. Pump 200 sx Pren	nium Plus. Set re	tainer @ 838' & pu	mp 200 sx Pr	emium Plus WOC.	
10/22/09 Drilled out retainer @ 838'.		•			
10/23/09 to 10/26/09 Resumed drilling. Drilled or	~				
10/27/09 to 10/28/09 Fell out of cement @ 4176'.		_		,	
Drill to approx 5300'. Getting back frac sand. Wa					
57', 4362-70', 4385-4406', 4452-63', 4468-74', 4476-8				66' & 5212-5308' (255)	
10/29/09 Acdz 5212-5308' w/2000 gal 15% NEFE		_	NEFE.		
10/30/09 Set 133 jts 2 7/8" PC tbg & 5 1/2" NC V		-		==0000	
11/2/09 Pressure tested to 500# for 30 mins w/no l	eak-off. Darold	Gray w/NMOCD w		FBMFOVERECORD	
11. Thereby certify that the foregoing is true and correct		<del></del>	AUGER		
Name (Printed Typed) Stormi Davis	Title Prod	uction Assistant		- 0000	
Stormi Davis			+ +	DEC 15 Kristof	
Signature A	Date 11/2	3/119	1 1	1 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	

REAU OF LAND MANAGEMENT THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by

Conditions of approval, if any are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office applicant to conduct operations

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false fictitiousor fraudulent statements or representations as to any matter within its jurisdiction