

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-25587
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name CONNIE C STATE
8. Well Number # 3
9. OGRID Number
10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
NEW MEXICO OCD FOR YESO ENERGY

3. Address of Operator

4. Well Location

Unit Letter K : 1980 feet from the E line and 1650 feet from the S line
Section 25 Township 19S Range 28E NMPM EDDY County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATIONS ☐ R AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

**Notify OCD 24 hrs. prior
To any work done.**

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RIH AND SET 5 1/2" CIBP @ 3127' - TOP WITH 25 SACKS - CIRCULATE PLUGGING MUD
2. SPOT 30 SACKS 1313' - WOC - TAG - TEST CASING
3. SPOT 30 SACKS @ 840' - TAG *8 5/8 C.S.G. Stm. + B. Salt 785'*
- * 4. CIRCULATE ~~30~~ SACKS FROM 300' TO SURFACE
5. INSTALL DRY HOLE MARKER AND CLEAN UP LOCATION

* #4 - Top Salt. @ 411' - Cmt plug from 461' - Surface.

STEEL PITS WILL BE USED FOR THIS PROCEDURE

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Mark Hol TITLE agent for ocd DATE 2/22/10

Type or print name
For State Use Only

E-mail address:

Telephone No.

APPROVED BY: Phil Harker
Conditions of Approval (if any):

TITLE Approval Granted providing work
is complete by 5/22/2010

DATE 2/23/2010