

Submit 1 Copy To Appropriate District
 Office
 District I
 1625 N French Dr., Hobbs, NM 88240
 District II
 1301 W Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 October 13, 2009

RECEIVED
CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505
RECEIVED
HOBBSUCD

WELL API NO. 30-015-31675
5. Indicate Type of Lease FEDERAL <input type="checkbox"/> STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name West Brushy 8 Federal SWD
8. Well Number 1
9. OGRID Number 14049
10. Pool name or Wildcat SWD; Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
Marbob Energy Corporation

3. Address of Operator
PO Box 227, Artesia, NM 88211-0227

4. Well Location
Unit Letter A : 660 feet from the North line and 330 feet from the East line
Section 8 Township 26S Range 29E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
2918' GL

RECEIVED
MAR 11 2010
NMOCD ARTESIA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	REPAIR AND ABANDON <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>
MULTIPLE COMPL. <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>	
OTHER <input type="checkbox"/>	OTHER: Mechanical Integrity Test <input checked="" type="checkbox"/>

13. Describe proposed or completed operations: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1/27/10 – Pressure tested tubing/casing annulus to 500# for 30 minutes. Held OK. Test witnessed and chart retained by Darold Gray with OCD – Artesia.

(See detailed procedure attached)

Spud Date: Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Diana J. Briggs TITLE: Production Manager DATE: March 8, 2010
 Type or print name: Diana J. Briggs E-mail address: production@marbob.com PHONE: (575) 748-3303
For State Use Only

APPROVED BY: Richard Inas TITLE: Compliance Officer DATE: 3/18/10
 Conditions of Approval (if any):

**MARBOB ENERGY CORPORATION
WEST BRUSHY 8 FEDERAL SWD #1 (Re-entry)
660 FNL 330 FEL, SEC. 8-T26S-R29E, UNIT A
30-015-31675, SWD; DELAWARE
EDDY COUNTY, NM**

- 01/22/10 RPL TOP JT TBG, CUT & RPL 8 5/8" & 5 1/2" CSG: 7:00 A.M. SAFETY MTG. RU. TP 400#. BLOW WELL DN TO GAS BUSTER. W/O WELDER & KILL TRUCK. 9:00 A.M. RU WATSON HOT OILER TO TBG. PMP 15 BBLS WTR. RD WATSON. WELDER TRIED HEATING UP BENT JT WHILE TRYING TO STRAIGHTEN W/ UT. BROKE @ BEND. ND LARKEN HEAD. WELDED ON COLLAR W/ 8' SUB. PULLED OFF SLIPS. GOT OFF ON/OFF TOOL. LD BAD JT. NU BOP. SWI. DUG OUT AROUND W/H. TRIED STRAIGHTENING 5 1/2" CSG. WOULDN'T STRAIGHTEN OUT. DUG 8' DEEP AROUND 8 5/8" CSG. READY FOR CUT & WELD ON MONDAY. SDFTD.
- 01/25/10 7.00 A.M. SAFETY MTG. POOH W/ 132 JTS IN DERRICK. PU & MU 5 1/2" 10-K AS-V RBP. RIH W/ 10 JTS. SET RBP @ 324'. GOT OFF ON/OFF TOOL POOH. RU MUSCLE KILL TRUCK. PMPD 3 BBLS FRESH ON RBP. ND BOP. RU WELDER. CUT 8 5/8". PULLED SLIPS. CUT 5 1/2" CSG. WELDED ON NEW 5 1/2" CSG & NEW 8 5/8" CSG DROP SLIPS. USED SAME 8 5/8" W/H. NU LARKEN HEAD. NU BOP. RIH W/ ON/OFF RTNR TOOL. LATCHED ONTO RBP. RLS & POOH. W/O NP ON/OFF TOOL. REDRESSED. 4:00 P.M. PU & MU 5 1/2" NP ON/OFF TOOL. RIH W/ 132 JTS. PU 2 7/8" PLASTIC I.D. REPLACEMENT JT. TAGGED VERSASET PKR. PULLED OFF 8'. RU MUSCLE WHITE KILL TRUCK & CIRC 118 BBLS PKR FL W/ FRESH. ND KILL TRUCK. ND BOP. LATCHED ONTO PKR SET PKR W/ 12 POINTS IN COMP. NU LARKEN HEAD. TEST TO 500#. TEST OK. HELD FOR 10 MINS. RD & RLS KILL TRUCK. SWI. SDFTD.
- 01/27/10 RU KILL TRUCK TO BACKSIDE OF WELL. PRESS UP TO 500# & CHART FOR 30 MINS. HAVE DAROLD GRAY FR/ OCD WITNESS CHART. HELD PSI. GOOD. RD KILL TRUCK. SWI.