UNITEDSTATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

LC067964

		REVISED
	ON.	ORMAPPROVED 4 B No 1004-0137 Dures March 31, 2007
5	Lease Serial	No

SUNDRY NUTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
abandoned well. Use Form 3160 - 3 (APD) for such proposals	

	is form for proposals ell. Use Form 3160 - 3			o ir mulan,	MAR 0 9 2010			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7 If Unit or CA/AgNINO COM ARTESI.			
1 Type of Well Gas Well Other					8 Well Name and No			
2 Name of Operator BOPCO, L.P.				9 API Well				
3a Address 3b PhoneNo (include area code) P.O. Box 2760 Midland TX 79702 (432)683-2277					30-015-20940 10 Field and Pool, or Exploratory Area			
4 Location of Well (Footage, Se	c , T , R , M , or Survey Desc	ription)		US (Dela	aware)			
UL C, SEC 34, T21S, R2	29E, 660' FNL, 1980'	11 County or Parish, State Eddy NM						
12. CHECK AI	PPROPRIATE BOX(ES)T	O INDICATE NATUR	RE OF NOTICE, F	REPORT, OR	OTHER DATA			
TYPE OF SUBMISSION TYPE OF ACTION								
X Noticeof Intent	X Acidize AlterCasing Casing Repair	Deepen X FractureTreat	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon		Water Shut-Off Well Integrity OtherPlug back BS			
Subsequent Report Final Abandonment Notice	Change Plans	New Construction Plug and Abandon Rhug Back			& perf Delaware			

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)

BOPCO, L.P. respectfully requests permission to recomplete the subject wellbore in the Delaware formation as follows:

- 1. MIRU PU Freepoint and jet cut 5-1/2" 17# N-80 casing at TOC (7645'). Circulate out w/ 9.5 ppg mud. Pull casing &
- 2. Spot 65 sx Class H cmt from 7555'-7735'
- 3. RIH w/ 5-1/2" 17# L-80 csg to 7555' & cmt to surface w/ 1300 sx EconoCem C + 5 pps Gilsonite & tail in w/ 75 sx VersaCem C + 0.40% CFR-3 + 5 pps + 1 pps salt. Circulate cmt to surface. Test csg to 5000 psi.
- 4 RIH w/ 3-1/8" titan guns and perforate the Delaware formation from 6868'-6880'
- 5. Acidize perfs w/ 1500 gals of 7.5% HCI
- 6 Evaluate inflow performance of well; fracture stimulate w/ YF120 ST+ w/ 100,000# 16/30 Brady w/ Propnet
- 7. Place well on pump.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)	1					
Valerie Truax	Title Regulatory Adi	ntle Regulatory Admin Assistant				
Signature Palent Smarf	Date 02/09/2010	APPROVED				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Арргoved by	Title	- pate MAR 8 2010				
Conditions of approval, if any, are attached Approval of this notice does not we certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon		/s/ Chris Walls BUREAU OF LAND MANAGEMENT				
Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for States any false, fictitious or fraudulent statements or representations as to ar		ly to make to any department or agency of the Onited				

Big Eddy Unit #38 30-015-20940 BOPCO, L.P. February 24, 2010 Conditions of Approval

- 1. Contact BLM 575-361-2822 a minimum of 4 hours prior to setting plug over Wolfcamp.
- 2. A minimum of a 3M BOP is required and must be tested prior to performing operations. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 3. Drill out existing CIBP at 10,114'. Spot 25 sx plug a minimum of 200' in length from 10,310'-10,110'. WOC and tag at 10,110' or shallower. (top of Wolfcamp at 10,260')
- 4. Tag plug across casing stub a minimum of 50' above stub.
- 5. Cement on the 5-1/2" production casing must come to surface if cement does not circulate contact the appropriate BLM office.
- 6. Surface disturbance beyond the existing pad must have prior approval.
- 7. Closed loop system required.
- 8. Completion report and subsequent sundry with well test and wellbore schematic required.
- 9. Well is outside of Delaware participating area. A commercial well determination will need to be submitted.

CRW 022410