Form 3160-5 (April2004)

9

UNITEDSTATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND, MANAGEMENT

FORMAPPROVED OM B No 1004-0137 Expires. March 31, 2007

K	M
· V	

· .	SUBBALL OF LAND MA		OCU PROBLE	Expires. March 31, 200	-1
Ŀ	BUREAU OF LAND MA	NAGEMENT	OCD Artes	5 Lease Serial No	
SUNDRY	NOTICES AND RE	EPORTS ON WEI	LS	NM 02887B	
	is form for proposals ell. Use Form 3160 - 3			6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No		
1 Type of Well		8. Well Name and No James Ranch Unit #15 9. API Well No			
2. Nameof Operator BOPCO, L.P.					
3a Address 3b PhoneNo.(include area code)			30-015-24780		
P.O. Box 2760 Midland TX 79702 (432)683-2277			10 Field and Pool, or Exploratory Area		
4 Location of Well (Footage, Sec, T, R, M, or Survey Description)			Wildcat (Strawn)		
UL M, Sec 8, T23S, R31E, 660' FSL, 100' FWL			11 County or Parish, State Eddy NM		
12. CHECK AI	PPROPRIATE BOX(ES)T	O INDICATE NATUR	E OF NOTICE, F	REPORT, OR OTHER DATA	
TYPEOF SUBMISSION		TYI	PEOF ACTION		
				Well Integrity X Other Plug back bandon & perf Strawn	ation thereof
following completion of the intesting has been completed. Fit determined that the site is read: BOPCO, L.P. respectful. 1. POOH w/ tbg and pact 2. RIH w/ CIBP Set CIB 3. Dump bail 35' of ceme	volved operations. If the operational Abandonment Notices shall y for final inspection.) ly requests permission cker. P at 13,350' Test CIE ent on plug.	on results in a multiple combe filed only after all require n to recomplete the BP to 2000 psi.	pletion or recompletion ments, including reclain subject wellbook	urred subsequent reports shall be filed with in a new interval, a Form 3160-4 shall be imation, have been completed, and the ope in the Strawn formation as TTACHED FOR ITIONS OF APPROV	e filed once erator has a follows
7. Flowtest and return to		ina 100 //6 1.3 5G	callsealers.	OF APPROV	/AL

TO THE PARTY AND THE PARTY OF THE PARTY

James Ranch Unit 15 30-015-24780 BOPCO March 25, 2010 Conditions of Approval

- 1. At final plugging a 240' plug (minimum of 25 sxs) must be set on top of existing CIBP at 14,450' to cover the top of the Morrow Formation at 14,378'.
- 2. Set CIBP at 13,350', pressure test and bail 35' of cement on top.
- 3. Surface disturbance beyond the existing pad must have prior approval.
- 4. Closed loop system required.
- 5. A minimum of a 5M BOP is required and must be tested prior to performing operations. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 6. Subsequent sundry with wellbore schematic and completion report are required.
- 7. Submit a commercial well determination when 6 months to 1 year production is recorded.

CRW 032510