



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

Don B
J.K. - Eng
8-103

GARY E. JOHNSON
Governor
Betty Rivera
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

RECEIVED

JAN 12 2004

OCD-ARTESIA

Yates Petroleum Corporation
105 South 4th Street
Artesia, New Mexico 88210

Form C-103 Report of Plugging for your *Caleb AVE ST #1- Sec 10- T12S- R27E - 30-005-00333*
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- OK For Release 1/20/04*
- ☒ 1. All pits have been filled and leveled.
 - ☒ 2. Rat hole and cellar have been filled and leveled.
 - ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
 - ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
 - ☒ 5. The dead men and tie downs have been cut and removed.
 - ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
 - ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

[Signature]
Name
Delg Supr
Title

date
1-8-04

Van Barton
Field Rep. II

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-00333
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA-1411
7. Lease Name or Unit Agreement Name Caleb AVE State
8. Well Number 1
9. OGRID Number 025575
10. Pool name or Wildcat Wildcat Mississippian

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Plug & Abandon <input type="checkbox"/>	2. Name of Operator Yates Petroleum Corporation
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	4. Well Location Unit Letter 0 : 660 feet from the South line and 1980 feet from the East line Section 10 Township 12S Range 27E NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3672' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7-18-2003 - Moved in and rigged up pulling unit and plugging equipment. Bled well down. Nipped down wellhead and nipped up BOP. Rigged up floor and tubing equipment. Worked packer loose. POOH with 2-3/8" tubing and packer. Shut well in for night.
7-19-21-2003 - Rigged up wireline. RIH with gauge ring and tagged up at 5877'. POOH and rigged down wireline. RIH with on/off tool and 174 joints of 2-3/8" tubing. Shut well in for night.
7-22-2003 - RIH with workstring and latched onto RBP. Worked RBP loose. POOH with RBP and workstring. Rigged up wireline. Dumped bailed 35' of cement on top of CIBP (existing) at 6350'. POOH with bailer. RIH with CIBP and set CIBP at 5750'. POOH and rigged down wireline. Shut well in for night.
7-23-2003 - RIH with tubing and tagged CIBP at 5750'. Shut well in for night.
7-24-2003 - Circulated hole with plugging mud. Spotted 25 sacks Class C Neat cement from 5750-5372'. Pulled up hole to 4822'. Spotted 25 sacks Class C Neat cement from

I hereby certify that the information above is true and complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE:

SIGNATURE Donna Clack TITLE REGULATORY COMPLIANCE TECH DATE 8-25-03

Type or print name DONNA CLACK E-mail address: Telephone No 505-748-1471
(This space for State use)

APPROVED BY [Signature] TITLE Wild Sep ID DATE JAN 26 2004
Conditions of approval, if any:

YATES PETROLEUM CORPORATION
Caleb AVE State #1
Section 20-T12S-R27E
Chaves County, New Mexico

SUNDRY NOTICE CONTINUED:

4822-4444'. POOH with tubing. Shut well in for night.
7-25-2003 - Rigged up wireline. RIH and perforated 4-1/2" casing at 2550'.
POOH and rigged down wireline. RIH with packer and tubing to 2240'. Shut well
in for night for rig repair.
7-26-28-2003 - Packer sheared. POOH with tubing and packer. RIH with new packer
and tubing and set packer at 2240'. Squeezed with 50 sacks Class C Neat cement.
Displaced to 2450'. Shut well in for night. WOC.
7-29-2003 - POOH with tubing and packer. RIH open ended and tagged plug at 2418'.
POOH with tubing. Rigged up wireline. RIH and perforated 4-1/1" casing at 2075'.
POOH and rigged down wireline. RIH with packer and tubing to 1760'. Set packer.
Squeezed with 50 sacks Class C Neat cement. WOC 4 hours. Rigged up wireline. RIH
and tagged plug at 1948'. POOH and rigged down wireline. Shut well in for night.
7-30-2003 - POOH with packer. Rigged up wireline. RIH and perforated 4-1/2" casing
at 1750'. POOH and rigged down wireline. RIH with packer and tubing. Squeezed with
50 sacks Class C Neat cement. WOC 4 hours. Rigged up wireline. RIH and tagged plug
at 1637'. POOH and rigged down wireline. POOH with packer and tubing. Rigged up
wireline. RIH and perforated at 307'. POOH and rigged down wireline. Rigged down
tubing equipment and floor. Nippled down BOP and 4-1/2" casinghead. Circulated
60 sacks Clsss C Neat cement down 4-1/2" casing and up to surface of 7" casing.
Shut well in for night. WOC.
7-31-2003 - Cement at surface. Dug out cellar. Cut off wellhead. Rigged down
pulling unit and plugging equipment. Installed regulation abandonment marker.
PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed July 30, 2003.

Anna Clack

xy
BB.03