

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Oil Cons.  
N.M. DIV-Dist. 2  
1301 W. Grand Avenue  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

J. C. Williamson

3. Address and Telephone No.

P.O. Box 16, Midland, TX 79702

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter M, 660' FSL & 660' FWL  
Sec. 10, T-20-S, R-29-E

5. Lease Designation and Serial No.

NM-0556290

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Gila Federal

8. Well Name and No.

1

9. API Well No.

30-015-26418

10. Field and Pool, or Exploratory Area

East Burton

11. County or Parish, State

Eddy, NM

RECEIVED

FEB 03 2004

OCD-ARTESIA

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Notify BLM 24 hrs. prior to moving in.
2. POOH w/ production equipment.
3. Set 5-1/2" CIBP @ 4800', cap w/ 35' of cmt. (Note: perforations 4857-5190').
4. Circulate hole w/ MLF.
5. Cut & pull 2900' of 5-1/2" csg. (Note: TOC @ 2924').
6. Spot 30 sx cmt. 2950-2850', WOC & tag.
7. Spot 35 sx cmt. 1165-1065', WOC & tag.
8. Spot 35 sx cmt. 297-197'.
9. Spot 10 sx cmt. 60-3'.
10. RDMO. Cut off wellhead, install dry hole marker, & clean location.

APPROVAL SUBJECT TO  
GENERAL REQUIREMENTS AND  
SPECIAL STIPULATIONS ATTACHED

14. I hereby certify that the foregoing is true and correct

Signed

*Roger Massey*

Agent

Date

01-26-04

(This space for Federal or State office use)

Approved by (ORIG. SGD.) ALEXIS C. SWOBODA

Title

PETROLEUM ENGINEER

Date

FEB 02 2004

Conditions of approval, if any: