

## OCD-ARTESIA

Form 3160-5  
(August 2007)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

JUN 28 2010

FORM APPROVED

OCD-ARTESIA

Expires July 31, 2010

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an  
abandoned well. Use Form 3160-3 (APD) for such proposals.

## SUBMIT IN TRIPLICATE - Other Instructions on page 2

1 Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5 Lease Serial No. NMLC028793C
2 Name of Operator Marbob Energy Corporation	6 If Indian, Allottee, or Tribe Name
3a Address PO Box 227 Artesia, NM 88211-0227	7 If Unit or CA Agreement Name and/or No. NMNM88525X
3b Phone No. (include area code) (575) 748-3303	8 Well Name and No. Burch Keely Unit #78
4 Location of Well (Footage Sec. T, R, M, or Survey Description) 2310 FSL 2310 FEL, Sec. 23-T17S-R29E, Unit J	9 API Well No. 30-015-23852
	10 Field and Pool, or Exploratory Area Grbg Jackson; SR-Q-Grbg-SA
	11 County or Parish, State Eddy Co., NM

## 12 CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13 Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

4/22/10 - 5/3/10

This well has been plugged &amp; abandoned.

(See detailed procedure attached)

Accepted as to plugging of the well bore.  
Liability under bond is retained until  
Surface restoration is completed.

Reclamation Due 10-30-10

14 I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Diana J Briggs

Title

Production Manager

Signature

Date

June 3, 2010

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any are attached. Approval of this notice does not warrant or  
certify that the applicant holds legal or equitable title to those rights in the subject lease  
which would entitle the applicant to conduct operations thereon.Title 18 U.S.C. Section 1001 AND Title 18 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United  
States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**MARBOB ENERGY CORPORATION  
BURCH KEELY UNIT #78 (P&A)  
2310 FSL 2310 FEL, SEC. 23-T17S-R29E, UNIT J  
30-015-23852, GRBG JACKSON; SR-Q-GRBG-SA  
EDDY COUNTY, NM**

4/22/10 P&A: SAFETY MTG. MIRU. OPEN WELL. ND W/H. NU BOP. RIH W/ GAUGE RING TO 2350'. POH. RIH W/ CIBP. SET @ 2340'. POH. RIH & TAG CIBP. PMP PLUGGING MUD. NO CIRC. SPOT 60 SX @ 2340'. POH. WOC. SDFTD.

4/23/10 SAFETY MTG. RIH & TAG @ 1791'. RIH & PERF @ 825'. POH. RIH W/ PKR. PMP 35 SX. WOC. SDFTD DUE TO WIND.

4/26/10 SAFETY MTG. RIH & TAG @ 651'. POH. CALL BLM. RIH & PERF @ 435'. RIH. NO RETURNS. PMP 113 SX. POH. WOC. RIH & TAG @ 639'. SDFTD.

4/27/10 SAFETY MTG. RIH & PMP 50 SX W/ 2% CACL2. POH. WOC. RIH & TAG @ 639'. POH. RIH & PMP 50 SX W/ 2% CACL2. WOC. RIH & TAG @ 618'. POH. RIH & PMP 20 SX W/ 4% CACL2. POH. SDFTD.

4/28/10 SAFETY MTG. RIH & TAG @ 618'. POH. RIH & PMP 50 SX W/ 2% CACL2 & PAPER. POH. WOC. RIH & TAG @ 537'. MIX PAPER AHEAD. PMP 25 SX W/ PAPER & 4% CACL2. POH. WOC. RIH & TAG @ 537'. POH. CALL MARK. PMP PAPER AHEAD. PMP 50 SX W/ 4% CACL2 & PAPER. POH. SDFTD.

4/29/10 SAFETY MTG. RIH & TAG @ 427'. CALL BLM. PMP 25 SX W/ 4% CACL2 & PAPER. WOC. RIH & TAG @ 427'. PMP 50 SX W/ 4% CACL2 & PAPER. POH. SDFTD.

4/30/10 SAFETY MTG. RIH & TAG @ 385'. CALL BLM. PMP 50 SX W/ 4% CACL2 & PAPER. POH. WOC. RIH & TAG @ 377'. SPOT 50 SX W/ 4% CACL2 & PAPER. POH. WOC. RIH & TAG @ 377'. SPOT 50 SX W/ 4% CACL2 & PAPER. POH. SDFTWE.

5/3/10 SAFETY MTG. RIH & TAG @ 377'. POH. CALL BLM. PMP 50 SX W/ 4% CACL2 & PAPER. POH. WOC. RIH & TAG @ 377'. PMP 50 SX W/ 4% CACL2 & PAPER. LOCKED UP. FILL BACKSIDE W/ 35 SX. DIG OUT W/H. INSTALL P&A MKR. CUT OFF ANCHORS. CLN LOC. MOVE OUT. SDFTD. FINAL REPORT.

**\*\*\*PLUGGED AND ABANDONED\*\*\***