OCD-ARTESIA

RW

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OMB No 1004-0137 Expires July 31, 2010 5. Lease Serial No. NM 100555

FORM APPROVED

					NM 100555			
Do not use this t	NOTICES AND REPO form for proposals t Use Form 3160-3 (A	o drill or to re	e-enter an	i .	6. If Indian, A	llottee or Tr	ube Name	
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No			
1. Type of Well	•				0.337-11.37	I NI-		
✓ Oil Well Gas Well Other					8 Well Name and No. Cooper 31 Federal #1H			
2. Name of Operator OGX Resources LLC					9. API Well No.: 30-015-36282			
3a Address P O Box 2064	3b. Phone No. (include area code)			10. Field and Pool or Exploratory Area				
Midland, Texas 79702	432-685-1287			Brushy Draw Delaware				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660° FNL & 660° FEL (A) Sec. 31, T25S, R29E					11. Country or Parish, State Eddy County, New Mexico			
12. CHEC	CK THE APPROPRIATE BO	X(ES) TO INDICA	ATE NATURE	OF NOTIO	CE, REPORT C	OR OTHER	DATA	
TYPE OF SUBMISSION	TYPE OF ACT				ION			
Notice of Intent	Acidize	Deepen		Prod	uction (Start/Res	sume)	Water Shut-Off	
The state of the s	Alter Casing	Fracture	Treat	Recl	amation	[Well Integrity	
Subsequent Report	Casing Repair	New Co	struction	Reco	mplete	[Other Add perforations	<u> </u>
	Change Plans		Abandon		porarıly Abando	n	-	
Final Abandonment Notice	Convert to Injection	Plug Bac	k 	Wate	er Disposal			
the proposal is to deepen direction. Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo	work will be performed or proved operations. If the operation Abandonment Notices must	ovide the Bond No on results in a mult	on file with BI iple completion	M/BIA, F or recomp	Required subsequences of the second s	uent reports interval, a F	s must be filed within 30 days Form 3160-4 must be filed one	;
Work to begin June 1, 2010. Durati	on 10 days.							
 MIRU - POH w/rods & tbg. Perforate Upper Bone Spring w/1 jspf (44 shots) at following: 6894' - 6904', 6922' - 6932', 6944' - 6954', 6967' - 6977' RIH w/RBP & pkr. Set RBP @ 6980'. Test RBP to 500 psi. Pull pkr to 6800 4. Acidize w/3000 gals 15% HCL & ball sealers. Swab test to determine further stimulation. Retrieve RBP & return well to production. 				SEE ATTACHED FOR CONDITIONS OF APPROVAL				
SUBJECT TO APPROVAL	LIKE BY STATE							
14. I hereby certify that the foregoing is to	rue and correct Name (Printe	d/Typed)		_				
Shelley Bush			Title Production Analyst					
Signature A Hills	y Bush	, n	ate 04/14/201	10	j		ADDDOVED	
3.5						<i></i>		

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Title Office JUN 1 7 2010

PSY Chris Walls

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OF FACE

entitle the applicant to conduct operations thereon

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Approved by



Cooper 31 Federal 1H 30-015-36282 OGX Resources LLC June 17, 2010 Conditions of Approval

- 1. Surface disturbance beyond the existing pad must have prior approval.
- 2. Closed loop system required.
- 3. A minimum of a 2M BOP is required and must be tested prior performing operations
- 4. Subsequent sundry with well bore schematic and completion report required.
- 5. Operator must file for down hole commingle approval with NMOCD and BLM prior to commingling production.

CRW 061710