## **OCD** Artesia

Form 3160-5 (August 2007)

(Instructions on page 2)


## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OMB No 10 Expires July		;E	=	V	E	L
5. Lease Serial No. NM-0610	JUL	1	9	20	010	

**SUNDRY NOTICES AND REPORTS ON WELLS** 

6 If Indian, Allottee or Tribe Name

	orm for proposals to drill or i Use Form 3160-3 (APD) for si		NMOCD ARTES					
1 Type of Well				7. If Unit of CA/Agreement, Name and/or No. S W Henshaw Premier Unit #17 8. Well Name and No #17				
2. Name of Operator Cameron Oil and Gas co. Inc			9. API Well No 30-015-37669	9. API Well No 30-015-37669				
3a Address PO Box 1455, Roswell NM 88202	3b Phone N	lo. (include area code)	10. Field and Pool or Ex					
4. Location of Well (Footage, Sec., T., I		575-627-3284		Henshaw: Grayburg, Weast 11 Country or Parish, State				
4. Location of Well (Footage, Sec., T., 2310 FNL & 2310 FEL Sec 18-T16S-R30-E SW	NE Property Control of the Control o		Eddy, NM					
12. CHEC	K THE APPROPRIATE BOX(ES) TO IN	OTICE, REPORT OR OTHE	E, REPORT OR OTHER DATA					
TYPE OF SUBMISSION		ACTION	LION					
Notice of Intent	= =	eepen	Production (Start/Resume)	Water Shut-Off				
		acture Treat	Reclamation	Well Integrity				
Subsequent Report		ew Construction	Recomplete	Other				
Final Abandonment Notice		ug and Abandon  ug Back	Temporarily Abandon Water Disposal					
	notified by telephone of this request.		Rugn	PROVED  Im Engineer  15 2010  B. Itale				
14. I hereby certify that the foregoing is t G David Sweeney	rue and correct Name (Printed/Typed)		CARLSB	LAND MANAGEMENT AD FIELD OFFICE				
G David Sweeney	1	Title VP of Operati	ons					
Signature Dow	Dueney	Date 07/15/2010						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by								
that the applicant holds legal or equitable entitle the applicant to conduct operations		n would Office		Date				
	USC Section 1212, make it a crime for an esentations as to any matter within its jurisdi		lifully to make to any departmen	t or agency of the United States any false,				



## BOP DIAGRAM

3000# Working Pressure