			1	
Submit 1 Copy To Appropriate District Offfice State of New Mexico			xico	Form C-103
District I Energy, Minerals and Natural Resources			ral Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO. 30 015 05168
1301 W. Grand Ave., Artesia, NM 88210				5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410				STATE X FEE
District IV Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				State A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				8. Well Number 1
1. Type of Well: Oil Well Gas Well Other			OFIVED.	1
2. Name of Operator			CEIVED	9. OGRID Number 270265
SandRidge Exploration & Production, LLC  3. Address of Operator		A	JG -6 2010	10. Pool name or Wildcat Grayburg
123 Robert S Kerr Ave, OKC OK 73102-6406		1	od , <b>v</b> 2010	Jackson SR-Q-G-SA
4. Well Location			CD ARTESIA	`
Unit Letter K: 1980 feet from the S line and 1980 feet from the W line				
Section 16	Township 17S		ange 31E	NMPM Eddy County
Section 10	11. Elevation (Show whe			Tivil III Eddy County
	3788 GR		,	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO				
				SEQUENT REPORT OF:
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORTH			_	
PULL OR ALTER CASING				
DOWNHOLE COMMINGLE	WOLTH LE COWN L	ш	OASINO/OEWENT	30B
BOWN IOLE COMMINITORE				
OTHER:			OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
proposed completion of recompletion.				
7-27-10 MI RU PU. Pld pmp.				
7-28-10 RIH w/pmp & rods. Hung well on. RU pmp trk. Attempted to load tubing but would not hold. RD pmp trk. Pld pmp & rods. ND				
WH, NU BOP. Pld tubing. Found 8 bad joints. RU Bo M onk testers. Tstd tbg to 6000 psi. PU & RIH w/BHA & 4 jts. Press to 3800 psi &				
collar parted, dropping tubing in hole. RD testers.				
7-29-10 RIH w/overshot. Worked over fish. POH w/OS & top jt of fish. Collar had split. RU Bo Monk testers. Tstd tbg to 3000 psi.				
Replaced 11 bad jts. RIH w/BHA & 125 jts 2-7/8" J-556.5# 8rd EUE tbg, set @ 3629'. RD testers. ND BOP, NU WH. 7-30-10 Ran pmp & rods. Hung well on. Loaded tbg w/4 bbls & press to 500 psi w/pmp – OK. RD pmp trk. RD PU.				
7-30-10 Ran pinp & rous. Trung wen on: Loaded tog w/4 obis & press to 300 psi w/pinp - OR. RD pinp tik. RD 1 O.				
<b>p</b>			·	
Spud Date:	Ria Re	elease Da	ite.	
Spud Bate.	Idg Id	cicase De		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
, , , , , , , , , , , , , , , , , , , ,				
Chair Ata	H,			
SIGNATURE UNW / Xal	hem & TITLI	EReg	ulatory Manager	DATE8/3/10
Type or print name Towi Stathers	E	il addess	tdetather @ = 1-	DUONE: 405 420 5692
Type or print name _Terri Stathem For State Use Only	E-mai	n address	s:tdstathem@sdr	rge.com PHONE: _405 429 5682
APPROVED BY: Daude	TITLE	Fe	to Frell SU	7V DATE 8-970
Conditions of Approval (if any):	0		, ———— <i>p</i>	
				W

Coff