<u>District I</u> 1625 N French Dr , Hobbs, NM 88240 District II
1301 W Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St. Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

SEP 23 2010

AMENDED

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate

NMOCD ARTESIA with Rule 116 on back side of form

30-015-30149

Release Notification and Corrective Action

MCB1027040333						OPERATOR			Initi	al Report		Final Report
Name of Company Merit Energy Company 14591						Contact Gene Holt						
Address 13727 Noel Rd, Suite 500 Dallas TX 75240						Telephone No. 432-683-0034						
Facility Name West Shugart 19-1,3,4,5,7 Battery						Facility Type Production						
Surface Owner BLM Mineral Owner						Lease No. NM 93772						
				LOCA	TIOI	N OF REI	LEASE					
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/V	Vest Line	County		******
N	19	188	31E	660	South		1980	West		Eddy		
Latitude 32.732 Longitude 103.9101												
NATURE OF RELEASE												
Type of Release Produced Water Volume of Release 180 bbls +/- JS Volume Recovered 130 bbls												
Source of Re		Date and H	our of Occurrence	urrence 9- Date and Hour of Discovery 9-16-10								
Was Immedia	ate Notice (16-10 4.00 PM										
☐ Yes ☐ Not Required												
By Whom?		Date and Hour										
Was a Watero	course Read	If YES, Volume Impacting the Watercourse.										
☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.*												
If a Watercou	rse was Im	pacted, Descri	be Fully.	•								
Describe Course of Broblem and Demodial Action Taken *Luchtning atules Shoreless and dead water took and for Took by June 14-14-14												
Describe Cause of Problem and Remedial Action Taken *Lightning strike fiberglass produced water tank and catch on fire. Tank burn down and release produced water inside dike area. Loco Hills Fire Dept. put out fire. Vacuum truck pick up produced water inside dike area and haul to disposal												
The second secon												
Describe Area	Affected a	and Cleanup A	ction Tak	en.* Spill contain	ed insid	e dike area. F	temove burnt tank	and co	ntaminated	l top soil. Ha	ul to c	ertified land
farm. Till in h	igh nitroge	n fertilizer. No	ote: 42' x	105' area south of	f the bat	tery outside o	f the dike was fou	ınd to b	e impacted	14" deep by	the rel	ease also. JS.
				is true and compl								
				nd/or file certain re se of a C-141 repor								
				investigate and re								
or the environ	ment In a	ddition, NMO	CD accep	tance of a C-141 r								
federal, state,	or local lav	vs and/or regu	lations.		-		OH GOVIG	EDI	ATTION	DHUGIO		
						OIL CONSERVATION DIVISION						
Signature							ι.	n Pi	/ ;/			
Printed Name	· Ioel Sick		A	Approved by	Dis Signed pBXus6	11/5	1 DKM	wer_	_			
T THICG IVAINC	, JUCI SISK						<u> </u>					
Title: Production Foreman					F	Approval Dad	EP 27 2010	E	Expiration l	Date:		
E-mail Addres	ss [.] joel sisk	@meritenergy	com /			Conditions of	Approval:					
							TION per OCD	Rules	and	Attached	Ш	
Date: 9-23-1 Attach Additi			ne 575-39	94-2574		REMEDIA	SUBMIT REME	DIATI	<u>on</u>	1		
			цу		(Suideiines.	SUBMIT REME BY: 10/27	120	10	2RP	- 11	2/
PMLBI	02704	2807				PRUPUSAL	<u></u> /0/	'	C	グリ	7	5 5