Form 3160-5 (August 2007)

DEPARTMENT OF THE INTERIOR

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RIQ NEW TOPPING

(Instructions on page 2)

UNITED STATES BUREAU OF LAND MANAGEMENT

	OMB No. 1004-0137
	Expires: July 31, 2010
ease Serial No.	

FORM APPROVED

LC-029431 6. If Indian, Allottee or Tribe Name

OCD Artesia

SUBMIT IN TRIPLICATE - Other instructions on page 2.			greement, Name and/or No.	
1. Type of Well			North Square Lake Unit NM101360X	
Oil Well Gas Well , Other		8. Well Name and		
		North So	quare Lake Unit 20	
2. Name of Operator CBS Operating Corp	٧,	30-0	15-04936`.`	
3a. Address P. O Box 2236 3b. Phone No. (include area code)		ode) 10. Field and Pool	10. Field and Pool or Exploratory Area	
Midland Texas 79702 432/685-0878		Square	Square Lake GB SA	
4. Location of Well (Footage, Sec., T., R., M., or Survey L.	Location of Well (Footage, Sec., T.,R,M., or Survey Description)		11. Country or Parish, State	
660' FNL & 1980' FEL UL	B Sec. 30 T16S R31	E Eddy NM		
12. CHECK THE APPROP	RIATE BOX(ES) TO INDICATE NATU	RE OF NOTICE, REPORT OR O	THER DATA	
TYPE OF SUBMISSION	T	YPE OF ACTION '		
Notice of Intent Acidize	Deepen Deepen	Production (Start/Resume	Water Shut-Off	
Alter Casi	ing Fracture Treat	Reclamation	Well Integrity	
Subsequent Report Casing Re	pair New Construction	Recomplete	Other	
Change Pl	lans Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice Convert to	o Injection Plug Back	Water Disposal		
8-24-10 - MI & RU Mayo Marrs. If 3030'. Spot 25 sacks cement on to RIH and tag at 2753'. RIH to 2627 RIH and tag at 2112'. POH with partial RIH and tag at 1520'. Perforate at RIH and tag at 1115'. Perforate at RIH and tag at 469'. Perforate at RIH and broke circulation. Pumper RIH and tag at 17'. Cut off wellhed Install dry hole marker and clean I	p of CIBP. Yes Spot 45 sacks cement acker to 1435'. Squeeze with 1420'. Squeeze with 25 sacks 100'. RIH and tag at 660'. Spot 30 sacks cement. and 30 sacks cement. and Circulated 10 sacks cement.	n 30 sacks cement. ks cement. pot 25 sacks cement. nent to surface.	RECEIVED SEP 21 2010 NMOCD ARTESIA ed as to plugging of the well bore.	
8-31-10 -Well plugged and abando	Liabilit	y under bond is retained until		
Reclamation Due Z	-27-11	Surface	restoration is completed.	
14. I hereby certify that the foregoing is true and correct. N	ame (Printed/Typed)			
M. A. Sirgo, III	Title E	ngineer		
Signature Co.: 1. Signature	Date Se	eptember 14,720	#n for record	
THIS	SPACE FOR FEDERAL OR S	TATE OFFICE USE		
Approved by			0.0010	
Conditions of approval, if any, are attached. Approval of this that the applicant holds legal or equitable title to those rights entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 12	in the subject lease which would Office	4	SER 1 6 2010	