Office Office	State of New Me	exico		Form C-103
District I	Energy, Minerals and Natu	ral Resources		October 13, 2009
1625 French Dr , Hobbs, NM 88240			WELL API NO.	
District OIL CONSERVATION DIVISION OIL CONSERVATION DIVISION		DIVISION	30-015-35929	
1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE		
-1000 Rio Brazós Rd., Aztec, NM 87410	Santa Fe, NM 8'	7505	6. State Oil & Ga	
District IV 1220 S. St. Francis Dr., Santa Fe, NM			0. State Off & G	is Lease No.
87505	IOEG AND DEDODES ON WELL			Y T *
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name BALLARD GBSA		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		8. Well Number 26-5		
PROPOSALS.)	<u></u>		8. Well Number	26-5
1. Type of Well: Oil Well	Gas Well Other		A CODID VI I	
2. Name of Operator TANDEM ENERGY CORPORATION		9. OGRID Number 36990		
3. Address of Operator		10. Pool name or Wildcat		
11490 WESTHEIMER RD, STE. 1000 HOUSTON, TX 77077		LOCO HILLS		
4. Well Location	<u> </u>			
	feet from theSOUTH_ lin	e and 307	feet from the	WEST line
	Township 18S Range		MPM EDDY	
Section 4	11. Elevation (Show whether DR			County
	11. Elevation (Show whether Div	, KKD, K1, OK, eic	··)	
Established Activities and Activitie	陳2		Harten and the	
12 Check	Appropriate Box to Indicate N	lature of Notice	Report or Other	Data
12. Check	Appropriate Box to indicate is	lature of Notice	, report of Office	Data
NOTICE OF I	NTENTION TO:	SUE	BSEQUENT RE	PORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WOI	RK 🔲	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DE	RILLING OPNS.	P AND A
LEINIE OLYVIVIET VOVIDOLI				
PULL OR ALTER CASING	_			
PULL OR ALTER CASING		CASING/CEMEN		
PULL OR ALTER CASING DOWNHOLE COMMINGLE				
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER:	MULTIPLE COMPL	CASING/CEMEN	NT JOB	
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com	MULTIPLE COMPL Deleted operations. (Clearly state all	CASING/CEMEN OTHER: pertinent details, a	NT JOB	
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMA	CASING/CEMEN OTHER: pertinent details, a	NT JOB	
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMACCOMPLETION.	OTHER: pertinent details, at C. For Multiple Co	NT JOB	
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMAGEOMPLETION. I CIRCULATE PLUGGING MUD - SPOT AG	OTHER: pertinent details, at C. For Multiple Co	NT JOB	
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS -	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMAGEOMPLETION. COMPLETION. CIRCULATE PLUGGING MUD - SPOT AG CIRCULATE TO SURFACE	OTHER: pertinent details, a C. For Multiple Co	NT JOB	wellbore diagram of
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS -	MULTIPLE COMPL pleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMA completion. I CIRCULATE PLUGGING MUD - SPOT AG - CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	OTHER: pertinent details, a: C. For Multiple Co 25 SACKS ON TOP	nd give pertinent dat ompletions: Attach v	
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS -	MULTIPLE COMPL pleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMA completion. I CIRCULATE PLUGGING MUD - SPOT AG - CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	OTHER: pertinent details, a: C. For Multiple Co 25 SACKS ON TOP	nd give pertinent dat ompletions: Attach v	wellbore diagram of
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS -	MULTIPLE COMPL pleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMArcompletion. I CIRCULATE PLUGGING MUD - SPOTAG - CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	OTHER: pertinent details, a: C. For Multiple Co 25 SACKS ON TOP	nd give pertinent dat ompletions: Attach v	RECEIVED OCT 14 2010
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS -	MULTIPLE COMPL pleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMArcompletion. I CIRCULATE PLUGGING MUD - SPOTAG - CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	OTHER: pertinent details, a: C. For Multiple Co 25 SACKS ON TOP	nd give pertinent dat ompletions: Attach v	RECEIVED
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS -	MULTIPLE COMPL pleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMArcompletion. I CIRCULATE PLUGGING MUD - SPOTAG - CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	OTHER: pertinent details, a: C. For Multiple Co 25 SACKS ON TOP	nd give pertinent dat ompletions: Attach v	RECEIVED OCT 14 2010
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS -	MULTIPLE COMPL pleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMArcompletion. I CIRCULATE PLUGGING MUD - SPOTAG - CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	OTHER: pertinent details, a: C. For Multiple Co 25 SACKS ON TOP	NT JOB	RECEIVED OCT 14 2010
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS -	MULTIPLE COMPL pleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMArcompletion. I CIRCULATE PLUGGING MUD - SPOTAG - CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	OTHER: pertinent details, a: C. For Multiple Co 25 SACKS ON TOP	nd give pertinent dat ompletions: Attach v	RECEIVED OCT 14 2010
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS -	MULTIPLE COMPL pleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMArcompletion. I CIRCULATE PLUGGING MUD - SPOTAG - CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	CASING/CEMEN OTHER: pertinent details, a: C. For Multiple Co 25 SACKS ON TOP CATION Offy OCD 2 To Only Wor	nd give pertinent dat ompletions: Attach v	RECEIVED OCT 14 2010
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS - 4. CUT OFF WELL HEAD AN ANCHO	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMARCOMPLETON. COMPLETON. CIRCULATE PLUGGING MUD - SPOT AG CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	CASING/CEMEN OTHER: pertinent details, a: C. For Multiple Co 25 SACKS ON TOP CATION Offy OCD 2 To Only Wor	nd give pertinent dat ompletions: Attach v	RECEIVED OCT 14 2010
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS - 4. CUT OFF WELL HEAD AN ANCHO	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMARCOMPLETON. COMPLETON. CIRCULATE PLUGGING MUD - SPOT AG CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	CASING/CEMEN OTHER: pertinent details, a: C. For Multiple Co 25 SACKS ON TOP CATION Offy OCD 2 To Only Wor	nd give pertinent dat ompletions: Attach v	RECEIVED OCT 14 2010
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS - 4. CUT OFF WELL HEAD AN ANCHO Spud Date:	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMARCOMPLETON. COMPLETON. CIRCULATE PLUGGING MUD - SPOT AG CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	OTHER: pertinent details, a C. For Multiple Co 25 SACKS ON TOP CATION Offy OCD 2 To Only Wor	nd give pertinent dat ompletions: Attach v	RECEIVED OCT 14 2010
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS - 4. CUT OFF WELL HEAD AN ANCHO Spud Date:	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMARCOMPLETON. CIRCULATE PLUGGING MUD - SPOT AG - CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	OTHER: pertinent details, a C. For Multiple Co 25 SACKS ON TOP CATION Offy OCD 2 To Only Wor	nd give pertinent dat ompletions: Attach v	RECEIVED OCT 14 2010
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS - 4. CUT OFF WELL HEAD AN ANCHO Spud Date:	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMAR completion. CIRCULATE PLUGGING MUD - SPOT AG CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	OTHER: pertinent details, at C. For Multiple Co 25 SACKS ON TOP CATION Offy OCD 2 To Only World ate:	nd give pertinent dat ompletions: Attach vone.	RECEIVED OCT 14 2010 NMOCD ARTESIA
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS - 4. CUT OFF WELL HEAD AN ANCHO Spud Date:	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMAR completion. CIRCULATE PLUGGING MUD - SPOT AG CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO	OTHER: pertinent details, at C. For Multiple Co 25 SACKS ON TOP CATION Offy OCD 2 To Only World ate:	nd give pertinent dat ompletions: Attach vone.	RECEIVED OCT 14 2010
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS - 4. CUT OFF WELL HEAD AN ANCHO Spud Date:	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMAR completion. CIRCULATE PLUGGING MUD - SPOT AG CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO Rig Release D Tabove is true and complete to the beat above is true and complete to the beat above is true.	OTHER: pertinent details, at C. For Multiple Co 25 SACKS ON TOP CATION Otify OCD 2 To CATION ate: est of my knowled	nd give pertinent dat ompletions: Attach von pletions Attach von p	RECEIVED OCT 14 2010 NMOCD ARTESIA
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS - 4. CUT OFF WELL HEAD AN ANCHO Spud Date: I hereby certify that the information SIGNATURE Type or print nameMARK HO	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMAR completion. CIRCULATE PLUGGING MUD - SPOT AG CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO Rig Release D Tabove is true and complete to the beat above is true and complete to the beat above is true.	OTHER: pertinent details, at C. For Multiple Co 25 SACKS ON TOP CATION Otify OCD 2 To CATION ate: est of my knowled	nd give pertinent dat ompletions: Attach von pletions Attach von p	RECEIVED OCT 14 2010 NMOCD ARTESIA
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS - 4. CUT OFF WELL HEAD AN ANCHO Spud Date:	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMAR completion. CIRCULATE PLUGGING MUD - SPOT AG CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO Rig Release D Tabove is true and complete to the beat above is true and complete to the beat above is true.	OTHER: pertinent details, at C. For Multiple Co 25 SACKS ON TOP CATION Otify OCD 2 To CATION ate: est of my knowled	nd give pertinent dat ompletions: Attach volume. ge and belief. DATE_10	RECEIVED OCT 1 4 2010 NMOCD ARTESIA /14/10 PHONE: 575-736-1366
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS - 4. CUT OFF WELL HEAD AN ANCHO Spud Date: I hereby certify that the information SIGNATURE Type or print nameMARK HO State Use Only	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMAR completion. CIRCULATE PLUGGING MUD - SPOT AG - CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO Rig Release D Tabove is true and complete to the b TITLE AGE SKINS E-mail address	OTHER: pertinent details, at C. For Multiple Co. 25 SACKS ON TOP CATION Office Only World ate: est of my knowled NTMARK@MA	nd give pertinent dat ompletions: Attach volume. ge and belief. DATE_10	RECEIVED OCT 1 4 2010 NMOCD ARTESIA /14/10 PHONE: 575-736-1366
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. RIH WITH CIBP SET @ 2411' - RIH 2. PERF @ 821' SPOT 25 SACKS - T 3. PERF @ 376' - PUMP 40 SACKS - 4. CUT OFF WELL HEAD AN ANCHO Spud Date: I hereby certify that the information SIGNATURE Type or print nameMARK HO	MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMAR completion. CIRCULATE PLUGGING MUD - SPOT AG - CIRCULATE TO SURFACE RS - INSTALL PA MARKER - LEVEL LO Rig Release D Tabove is true and complete to the b TITLE AGE SKINS E-mail address	OTHER: pertinent details, at C. For Multiple Co 25 SACKS ON TOP CATION Otify OCD 2 To CATION ate: est of my knowled	nd give pertinent dat ompletions: Attach volume. ge and belief. DATE_10	RECEIVED OCT 14 2010 NMOCD ARTESIA

Approval Granted providing work is complete by

TANdem
Ballard GBSA #26-5

