0.00	State of New M	lexico	Form C-103
Office District I	Energy, Minerals and Na		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		7	WELL API NO.
District II	OIL CONSEDUATIO	N DIVISION 3	30-015-26781
1301 W. Grand Ave., Artesia, NM 88210			Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410			STATE 🛛 FEE 🗌
District IV	Santa Fe, NM 8	37505	State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
87505	ICES AND REPORTS ON WELL	C	7 Lagge Name of Unit Agreement Name
	DSALS TO DRILL OR TO DEEPEN OR P		7. Lease Name or Unit Agreement Name
	CATION FOR PERMIT" (FORM C-101)		CI West Coon Unit
PROPOSALS.)	,		GJ West Coop Unit 8. Well Number 98
1. Type of Well: Oil Well	Gas Well Other		
2. Name of Operator		Ġ	9. OGRID Number
COG Operating LLC			229137
3. Address of Operator			10. Pool name or Wildcat 97558
550 W. Texas Ave., Suite 1300	Midland, TX 79701		GJ; 7RVS-QN-GB-Glorieta-Yeso
Well Location			
Unit Letter <u>E</u>	1845' feet from the Nor	th line and6	feet from the <u>West</u> line
Section 22	Township 17S	Range 29E	NMPM County Eddy
	11. Elevation (Show whether D		
		7' GR	
Pit or Below-grade Tank Application		, , , , , , , , , , , , , , , , , , , ,	The second secon
Pit typeDepth to Ground		water well Distan	ice from nearest surface water
Pit Liner Thickness: mi	₹		truction Material
12. Check	Appropriate Box to Indicate	Nature of Notice, Re	eport or Other Data
NOTIOE OF I	ITENITION TO	l QUIDO	FOLIENT DEPORT OF
NOTICE OF I	NTENTION TO:		EQUENT REPORT OF:
PERFORM REMEDIAL WORK		REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	LING OPNS. P AND A
	CHANGE PLANS		LING OPNS. P AND A
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS	COMMENCE DRILL CASING/CEMENT	LING OPNS. P AND A D
TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:	CHANGE PLANS MULTIPLE COMPL	COMMENCE DRILL CASING/CEMENT OTHER: Add pe	LING OPNS. P AND A DOB DOBBETS
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all	COMMENCE DRILL CASING/CEMENT. OTHER: Add per lipertinent details, and get lipertinent details.	ING OPNS. P AND A JOB erfs give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed w	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all	COMMENCE DRILL CASING/CEMENT. OTHER: Add per lipertinent details, and get lipertinent details.	LING OPNS. P AND A DOB DOBBETS
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all	COMMENCE DRILL CASING/CEMENT. OTHER: Add per lipertinent details, and get lipertinent details.	ING OPNS. P AND A JOB erfs give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed w	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all	COMMENCE DRILL CASING/CEMENT. OTHER: Add per lipertinent details, and get lipertinent details.	ING OPNS. P AND A JOB Gerfs give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult	COMMENCE DRILL CASING/CEMENT . OTHER: Add per liptonent details, and giple Completions: Attack	ING OPNS. P AND A JOB erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Set	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult	COMMENCE DRILL CASING/CEMENT . OTHER: Add per liptonent details, and giple Completions: Attack	ING OPNS. P AND A JOB Gerfs give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes.	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult	COMMENCE DRILL CASING/CEMENT . OTHER: Add per liptonent details, and giple Completions: Attack	ING OPNS. P AND A JOB erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Set	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult	COMMENCE DRILL CASING/CEMENT . OTHER: Add per liptonent details, and giple Completions: Attack	ING OPNS. P AND A JOB erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes.	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult	COMMENCE DRILL CASING/CEMENT . OTHER: Add per liptonent details, and giple Completions: Attack	ING OPNS. P AND A JOB erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr.	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand	COMMENCE DRILL CASING/CEMENT. OTHER: Add pertinent details, and giple Completions: Attack	ING OPNS. P AND A DOB
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Set holes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 ga	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand	COMMENCE DRILL CASING/CEMENT. OTHER: Add pertinent details, and giple Completions: Attack	ING OPNS. P AND A JOB erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comon of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gatholes.	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand	COMMENCE DRILL CASING/CEMENT. OTHER: Add per I pertinent details, and giple Completions: Attack of the completions of the completion of the comple	ING OPNS. P AND A DOB SIDE PAND A DOB SIDE PAND A DOB SIDE PAND A DOB PAND A
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comon of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gatholes. 9/9/10 Release RBP. F	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand als acid. Frac w/ 173,754 g	COMMENCE DRILL CASING/CEMENT. OTHER: Add per liple Prince details, and giple Completions: Attack of the completions of the completion of the compl	ING OPNS. P AND A DOB SIDE PAND A DOB SIDE PAND A DOB SIDE PAND A DOB PAND A
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comon of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gatholes. 9/9/10 Release RBP. F	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand	COMMENCE DRILL CASING/CEMENT. OTHER: Add per liple Prince details, and giple Completions: Attack of the completions of the completion of the compl	erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion dock @ 3940-4250 w/ 1SPF,26 16/30 Ottawa sand, 26,758#
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comon of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gatholes. 9/9/10 Release RBP. F	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand als acid. Frac w/ 173,754 g	COMMENCE DRILL CASING/CEMENT. OTHER: Add per liple Prince details, and giple Completions: Attack of the completions of the completion of the compl	ING OPNS. P AND A DOB SIDE PAND A DOB SIDE PAND A DOB SIDE PAND A DOB PAND A
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comon of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gatholes. 9/9/10 Release RBP. F	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand als acid. Frac w/ 173,754 g	COMMENCE DRILL CASING/CEMENT. OTHER: Add per liple Prince details, and giple Completions: Attack of the completions of the completion of the compl	erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion dock @ 3940-4250 w/ 1SPF,26 16/30 Ottawa sand, 26,758#
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comon of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gatholes. 9/9/10 Release RBP. F	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand als acid. Frac w/ 173,754 g	COMMENCE DRILL CASING/CEMENT. OTHER: Add per liple Prince details, and giple Completions: Attack of the completions of the completion of the compl	LING OPNS. PAND A DOB DOB PAND A
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comon of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gatholes. 9/9/10 Release RBP. F	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand als acid. Frac w/ 173,754 g	COMMENCE DRILL CASING/CEMENT. OTHER: Add per liple Prince details, and giple Completions: Attack of the completions of the completion of the compl	erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion dock @ 3940-4250 w/ 1SPF,26 16/30 Ottawa sand, 26,758#
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comon of starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gatholes. 9/9/10 Release RBP. F	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand als acid. Frac w/ 173,754 g	COMMENCE DRILL CASING/CEMENT. OTHER: Add per liple Prince details, and giple Completions: Attack of the completions of the completion of the compl	LING OPNS. PAND A DOB DOB PAND A
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Set holes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gat 16/30# Siberprop Sand. 9/9/10 Release RBP. Fellonger Starting any proposed work or recompletion.	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand alls acid. Frac w/ 173,754 g BH w/ 132 jts 2-7/8" tbg, S -1/2 x 20 pump. Hang on wear above is true and complete to the	COMMENCE DRILL CASING/CEMENT. OTHER: Add per I pertinent details, and giple Completions: Attack of the completions of the completion of the comple	erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion dock @ 3940-4250 w/ 1SPF,26 16/30 Ottawa sand, 26,758# RECEIVED SEP 3 0 2010 NMOCD ARTESIA
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Set holes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gat 16/30# Siberprop Sand. 9/9/10 Release RBP. Fellonger Starting any proposed work or recompletion.	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand alls acid. Frac w/ 173,754 g BH w/ 132 jts 2-7/8" tbg, S -1/2 x 20 pump. Hang on wear above is true and complete to the	COMMENCE DRILL CASING/CEMENT. OTHER: Add per I pertinent details, and giple Completions: Attack of the completions of the completion of the comple	erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion dock @ 3940-4250 w/ 1SPF,26 16/30 Ottawa sand, 26,758# RECEIVED SEP 3 0 2010 NMOCD ARTESIA
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gatholes. 9/9/10 Release RBP. F. 9/12/10 RIH w/ 2-1/2 x 1 I hereby certify that the information grade tank has been/will be constructed or cons	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state al ork). SEE RULE 1103. For Mult Q 4286. Dump 1 sx sand als acid. Frac w/ 173,754 g RH w/ 132 jts 2-7/8" tbg, S -1/2 x 20 pump. Hang on w above is true and complete to the r closed according to NMOCD guidelines.	COMMENCE DRILL CASING/CEMENT. OTHER: Add per lipertinent details, and giple Completions: Attack lipertinent details, and giple Completions details, and giple Complet	erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion dock @ 3940-4250 w/ 1SPF,26 16/30 Ottawa sand, 26,758# RECEIVED SEP 3 0 2010 NMOCD ARTESIA and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Set holes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gat 16/30# Siberprop Sand. 9/9/10 Release RBP. Fellonger Starting any proposed work or recompletion.	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Mult 4286. Dump 1 sx sand alls acid. Frac w/ 173,754 g BH w/ 132 jts 2-7/8" tbg, S -1/2 x 20 pump. Hang on wear above is true and complete to the	COMMENCE DRILL CASING/CEMENT. OTHER: Add per I pertinent details, and giple Completions: Attack of the completions of the completion of the comple	erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion dock @ 3940-4250 w/ 1SPF,26 16/30 Ottawa sand, 26,758# RECEIVED SEP 3 0 2010 NMOCD ARTESIA
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gatholes. 9/9/10 Release RBP. Fellow Point of the information grade tank has been/will be constructed of SIGNATURE.	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple acid. Frac w/ 173,754 grades	COMMENCE DRILL CASING/CEMENT. OTHER: Add per l pertinent details, and giple Completions: Attack l on top. Perf Pado als gel, 204,792# N @ 4183'. well. best of my knowledge as _, a general permit _ or _ or _ Agent for COG	erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion dock @ 3940-4250 w/ 1SPF,26 16/30 Ottawa sand, 26,758# RECEIVED SEP 3 0 2010 NMOCD ARTESIA and belief. I further certify that any pit or below- ran (attached) alternative OCD-approved plan DATE 9/14/10
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Set holes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gat 16/30# Siberprop Sand. 9/9/10 Release RBP. Ferror Siberprop Sand. 9/9/10 RIH w/ 2-1/2 x 10 Interest the information grade tank has been/will be constructed of SIGNATURE Type or print name Chasity Jack	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple acid. Frac w/ 173,754 grades	COMMENCE DRILL CASING/CEMENT. OTHER: Add per l pertinent details, and giple Completions: Attack l on top. Perf Pado als gel, 204,792# N @ 4183'. well. best of my knowledge as _, a general permit _ or _ or _ Agent for COG	erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion dock @ 3940-4250 w/ 1SPF,26 16/30 Ottawa sand, 26,758# RECEIVED SEP 3 0 2010 NMOCD ARTESIA and belief. I further certify that any pit or below- ran (attached) alternative OCD-approved plan DATE 9/14/10
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Setholes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gatholes. 9/9/10 Release RBP. Fellow Point of the information grade tank has been/will be constructed of SIGNATURE.	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple acid. Frac w/ 173,754 grades	COMMENCE DRILL CASING/CEMENT. OTHER: Add per l pertinent details, and giple Completions: Attack l on top. Perf Pado als gel, 204,792# N @ 4183'. well. best of my knowledge as _, a general permit _ or _ or _ Agent for COG	erfs give pertinent dates, including estimated date ch wellbore diagram of proposed completion dock @ 3940-4250 w/ 1SPF,26 16/30 Ottawa sand, 26,758# RECEIVED SEP 3 0 2010 NMOCD ARTESIA and belief. I further certify that any pit or below- ran (attached) alternative OCD-approved plan DATE 9/14/10
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Set holes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gat 16/30# Siberprop Sand. 9/9/10 Release RBP. Fereight Siberprop Sand. 9/9/10 Release RBP. Fereight Signature Signature Signature Chasity Jack For State Use Only	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state al ork). SEE RULE 1103. For Mult Q 4286. Dump 1 sx sand als acid. Frac w/ 173,754 g RH w/ 132 jts 2-7/8" tbg, S -1/2 x 20 pump. Hang on v above is true and complete to the relosed according to NMOCD guideline. TITLE son E-mail address: cjacks	COMMENCE DRILL CASING/CEMENT. OTHER: Add per lipertinent details, and giple Completions: Attack lipertinent	ING OPNS. PAND A DOB
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 8/10/10 RIH w/ RBP. Set holes. 8/22/10 Set pkr @ 4293'. 8/23/10 Release pkr. 9/6/10 Acidize w/ 3,000 gat 16/30# Siberprop Sand. 9/9/10 Release RBP. Ferror Siberprop Sand. 9/9/10 RIH w/ 2-1/2 x 10 Interest the information grade tank has been/will be constructed of SIGNATURE Type or print name Chasity Jack	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state al ork). SEE RULE 1103. For Mult Q 4286. Dump 1 sx sand als acid. Frac w/ 173,754 g RH w/ 132 jts 2-7/8" tbg, S -1/2 x 20 pump. Hang on v above is true and complete to the relosed according to NMOCD guideline. TITLE son E-mail address: cjacks	COMMENCE DRILL CASING/CEMENT. OTHER: Add perlinent details, and giple Completions: Attack and and gipl	ING OPNS. PAND A DOB

Sm