<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED State of New Mexico

FEB 07 2011

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Energy Minerals and Natural Resources

NMOCD ARTESibrait 2 Copies to appropriate ct Office in accordance with Rule 116 on back side of form

	-		Rele	ase Notifica	tio	n and Cori	ective Acti	on			
Kmw 1104139783						OPERATO					
Name of Company: Chesapeake Operating, Inc. /47/77						Contact: Bradley Blevins					
Address: 50					Telephone No.: (505) 391-1462, ext. 6224						
Facility Nan					Facility Type: Production Well						
Surface Own Bureau of La			ernment-			: United States Management	Lease	Lease No.: API #30-015-034/3			
LOCATION OF RELEASE											
Unit Letter Section Township Range 30E Feet from the 660						North/South Line South Feet from the 660		East/West East	Line	County Eddy	
Latitude: Longitude:											
NATURE OF RELEASE Type of Release: Petroleum and/or Production fluids Volume of Release: ~35 barrels Volume Recovered: 25 barrels											
Source of Relea			duction fla	iids	Volume of Release: ~35 barrels Volume Recovered: 25 barrels Date and Hour of Occurrence: Date and Hour of Discovery:						
Source of Ker	ease. Sturn	ng box				11 @ 11:00 am	January 29, 2011 @ 1:00 pm				
Was Immedia	te Notice C				If YES, To Whom?						
				No 🗌 Not Requ							
By Whom? Bradley Blevins, Chesapeake Operating, Inc. Was a Watercourse Reached?						Date and Hour: January 29, 2011, 1:00 pm If YES, Volume Impacting the Watercourse:					
Was a Watercourse Reached? ☐ Yes ☑ No						Not Applicable					
If a Watercou	rse was Im	pacted, Desc	ribe Fully	.* Not Applicable		. 					
Describe Cause of Problem and Remedial Action Taken: The Stuffing Box on well malfunctioned causing release of production fluids onto location. 25 of the 35 barrels released were recovered and contaminated soil was excavated and hauled to a state approved land farm. Soil Samples were taken and submitted to Cardinal Laboratories for testing. Upon receiving acceptable results from Cardinal Laboratories, the affected area will be backfilled, and returned to proper conditions.											
Describe Area	Describe Area Affected and Cleanup Action Taken:										
regulations all public health of should their op	operators and the enviro erations have the environs have the ent. In additional ent.	e required to nment. The a ve failed to ad lition, NMOC	report and cceptance lequately it accepta	s true and complete for file certain relea of a C-141 report be avestigate and remonder of a C-141 report control of a C-141 rep	ase n by the ediate	otifications and p e NMOCD marke e contamination the oes not relieve the	erform corrective d as "Final Report hat pose a threat to e operator of response.	actions for rele " does not rele ground water insibility for c	eases whi leve the o r, surface ompliance	ch may endanger perator of liability water, human health e with any other	
						OIL CONSERVATION DIVISION					
Signature:							4	II. x.			
Printed Name: Bradley Blevins						Approved by District Supervisor 1/4 Branua					
Title: Field Technician						Approval Date: 2//7/// Expiration Date:					
E-mail Address: bblevins@chkenergy.com						Conditions of Ap	-		Attach	ned 🗍	
Date: November 3, 2010 Phone: (505) 391-1462 ext. 6224 Attach Additional Sheets If Necessary						uidelines. SU	on per OCD Ru BMIT REMEDI T LATER THAI	IATION	2 K	P-602	
							///				