

OOD-ARTESIA

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.


SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well [X] Oil Well [] Gas Well [] Other
2. Name of Operator SandRidge Expl And Prod LLC
3a. Address 2130 W. Bender, Hobbs, NM 88240
3b. Phone No. (include area code) 575-738-1739 ext 117
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UL D, Sec 27, T-17-S R-31-E 15' FNL 1262' FWL

5. Lease Serial No. NMLC029419B
6. If Indian, Allottee or Tribe Name
7. If Unit or CA/Agreement, Name and/or No. NMNM071030XA
8. Well Name and No. Skelly Unit #263
9. API Well No. 30-015-29184
10. Field and Pool, or Exploratory Area Grayburg Jackson; SR-Q-G-SA
11. County or Parish, State Eddy Co; NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

Table with columns TYPE OF SUBMISSION and TYPE OF ACTION. Includes checkboxes for Notice of Intent, Subsequent Report, Final Abandonment Notice, Acidize, Deepen, Production (Start/Resume), Water Shut-Off, etc.



13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-5 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

02/17/11 MIRU rig and cementing equipment. NU BOP and EPA pan. RIH w/112 jts tbg. (3528'). Well started flowing, closed in shut down.
02/18/11 Well had 150 psi on tbg. Bleed down to pit. RIH w/ tbg to 3720'. Circulate hole with mud laden fluid. Well started flowing. Spot 40 sx class C cement @ 3720' and displace to 3320'. Closed well in and WOC.
02/21/11 rig up Gray Wireline. Could not get down. Rigged down Gray WL. RIH w/ 7/8 rod and tag cement @ 3714'. POH. RIH w/ wiring and cut tbg @ 3500'. No Change. RIH andcut tbg @ 3400'. No change. Back off tbg @ 1842'. Screw back on tbg. Free point tbg and free @ 3024'. Cut tbg and came out of hole w/ 96 jts. RIH to 3024. Close well in shut down.
02/22/11 Load hole w/ mud laden fluid. Spot 30 sx class C cement @ 3024'. Pull out of cement. WOC Tag plug @ 3760'. POH to 2160'. Spot 50 sx class C cement @ 2160'. Pull out of cement and WOC.
02/23/11 Tagged plug @ 1876'. Spot 60 sx class C cement @ 1876'. POH and WOC.
02/24/11 tagged plug @ 1386'. POH to 600'. Pump 65 sx class C cement and circulate to surface. ND BOP and EPA pan and Rigged down. Moved off.
02/28/11 Move in back hoe and welder. Dig out cellar. Cut off well head and weld on Dry Hole Marker. Cut off dead men. Back fill cellar. Clean location and move off.

RECLAMATION DUE 8-23-11

Accepted as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Signature: Linda Guthrie, Title: Reg Manager, Date: 3/4/11

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by: [Signature], Title: [Blank], Date: MAR 15 2011, Office: [Blank]

(Instructions on page 2)

Accepted for record NMOCD

Handwritten signature and date: 3/21/2011

BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE