


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

### Release Notification and Corrective Action

HKMW 1035634128

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company - EnerVest Operating LLC 143199	Contact - Elroy Ardoin
Address - 1001 Fannin Street, Suite 800, Houston, TX 77002	Telephone No. (713) 495 6534
Facility Name - Robinson Federal Tank Battery	Facility Type - Tank Battery for Robinson Federal #2
Surface Owner - BLM	Mineral Owner
API No. 3001524134	

#### LOCATION OF RELEASE

Unit Letter	Section 35	Township 17S	Range 29E	Feet from the	South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	-----------------	--------------	---------------	------------	---------------	----------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE

Type of Release - Oil	Volume of Release estimated 40bbls	Volume Recovered 20bbls
Source of Release - Hole in nipple in tank	Date and Hour of Occurrence? 7/2/2010 - 10:00AM	Date and Hour of Discovery 7/2/2010 - 12:00PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos - BLM - Carlsbad office	
By Whom? Robert Griffin - EnerVest Production foreman	Date and Hour - 12:00PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

#### Describe Cause of Problem and Remedial Action Taken.\*

A hole in nipple of holding tank attached to flow line was source of oil spill. The spill was contained within the tank battery dike area. An estimated 40bbls was spilled and 20bbls was recovered and pumped back into storage tank. The faulty nipple was replaced immediately. The spill area within the tank battery dike is 12yds X 25yds. This tank battery is for the Robinson Federal #2 API #3001524134. Remediation action taken was to pump 20bbls of freestanding oil back into tank. No further remedial action has been taken yet. A sampling investigation will be conducted to delineate the extent of contamination. A sampling report will be submitted to OCD with a remediation plan to be implemented upon NMOC D approval.

#### Describe Area Affected and Cleanup Action Taken.\*

This oil spill was completely contained within the bermed area of tank battery facility. No other area was impacted. The spill area within the tank battery dike is 12yds X 25yds. Recommended remediation is to conduct "dig & haul" operation with lab analysis. Contaminated soil will be removed to a locally approved disposal site and back filled with clay based impermeable soil. A closing report will then be submitted to OCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Elroy Ardoin	Signed By:	
Title: HS&E Coordinator	Approved by District Supervisor	Approval Date: 3/7/11
E-mail Address: eardoin@enervest.net	Expiration Date:	Attached <input type="checkbox"/>
Date: 7/9/2010 Phone: (713) 495 6534	Conditions of Approval:	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

4/7/11

2 RP-518

**Bratcher, Mike, EMNRD**

---

**From:** Andy Price [andyprice@grandecom.net]  
**Sent:** Friday, July 09, 2010 10:21 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Elroy Ardoin  
**Subject:** EnerVest Operating - c141 spill report - Robinson Fed. #2 Tank Battery  
**Attachments:** c141 - EnerVest- Robinson Fed. Tank Battery spill rpt-7-9-2010.pdf

Mike,

This is the spill I discussed with you on the phone. This was reported immediately to BLM. I will keep you updated with each step of our remediation process and submit the appropriate documentation.  
Thank you.

Andy Price  
REM  
432-352-6400  
Baseline Solutions, LLC  
511 W. Ohio St., Ste. 400  
Midland, TX, 79701