Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD-ARTESIA


FORI	N F	APRO	VE	ט
OMB N	Ю.	1004	1-01	35
EXPIRES	٠ ٨	/arch	31	200

SUNDRY NOTICES AND REPORTS ON WELLS		5	5. Lease Serial No.				
Do not use this form for proposals to drill or to re-enter an			NMNM 36379; K 4562 6. If Indian, Allottee or Tribe Name				
	e Form 3160-3 (APD) for such pro	oposals		. If Indian, Allottee	or tribe Name		
SL	IBMIT IN TRIPLICATE		-	/ Unit or CA Agre	ement Name and No.		
1a. Type of Well 🔽 Oil Well 🔲 Ga	s Woll Other			. Officer on Agree	ement Name and No.	·	
Ta. Type of Well Oli Well Ga	s Well	· · · · · · · · · · · · · · · · · · ·	8	Well Name and I	No.		
2. Name of Operator		"		Cotto	n Draw Unit 135H		
DEVON ENERGY PRODUCT	ION COMPANY, LP		9	API Well No.	00-		
Address and Telephone No.				30-015-	38533		
20 N. Broadway, Oklahoma City, Ok 73102-8260 405-235-3611			1	10. Field and Pool, or Exploratory			
4. Location of Well (Report location clearly and in accordance with Federal requirements)*			L	Paduca; Bone Spring			
200 FSL 1600 FWL N SEC 2 T25S R31E				11. County or Parish State			
BHL: 2600 FSL & 986 FWL L SEC 35 T24S R31E				Eddy NM			
12. CHECK TYPE OS SUBMISSION	APPROPRIATE BOX(s) TO INI		OTICE, REPORTE OF ACTION	r, or other dat	TA		
TIFE OS SUBIVIISSION		[]		(Chart Day			
✓ Notice of Intent	☐ Acidize☐ Alter Casing	☐ Deepen ☐ Fracture Treat	Reclamatio	(Start/Resume)	☐ Water Shut-Of☐ Well Integrity	T	
			Recomplete		✓ Other Ashton	Rin	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporaril		7.OHOH	, ,,9	
13. Describe Proposed or Completed Operations (C	Convert to Injection	Plug Back Tinent dates, including estimated	Water Disp		oximate duration thereof. If	the proposal	
the Bond No. on file with BLWBIA. Required subsequinterval, a Form 3160-4 shall be filed once testing has determined that the site is ready for final inspection) Devon Energy Production Comp Services rig. The rig plat is attact the surface casing has been run	been completed. Final Abandonment Notice pany, L. P. respectfully requ ched. This rig will be used o	es shall be filed only after all requests to set the surfonly to set the surfa	ace casing unce casing an	sing an Ashton d will leave the	Oilfield		
The surface casing will be run at cap welded onto the surface callocation. The BLM will be notified BLM Onshore Orders No.2 when	sing. Another rig will be or ed when the Ashton rig m	n location within 90 oves off location. T location.	days after the surface ca	he Ashton rig h asing will be te		APR 04 2011	
14. Thereby certify that the foregoing is t	rue and correct	 					
Signed July 5	Name Title	Judy A. Barnett Regulatory Spe		Date	3/21/2011		
(This space for Federal or State Office us	e)						
Approved by Conditions of approval, if any:	Title			Date			
Thie 16 U.S.S. Seelion 1001; makes it a chime for any	рёгэон кножіндіу ана мішықу тө тішке апу	ucparament or agency or the one within its jurisdiction.	нев отвісэ вну твіве,	TICINIOUS OF TRUBUICHES	истенз от гергезеницон.	s to uny matter	

*See Instruction on Reverse Side







Cotton draw Unit 135H Devon Energy Production Company, L. P. 30 March 2011 Conditions of Approval

- 1. Surface disturbance beyond the originally approved pad must have prior approval.
- 2. Option Setting surface casing with Ashton Rig
 - a. Notify the BLM when removing the Ashton Oilfield Services Rig.
 - b. Notify the BLM when moving in the H&P Flex Rig. Rig to be moved in within 90 days of notification that Ashton Oilfield Services Rig has left the location. Failure to notify or have rig on location within 90 days will result in an Incident of Non-Compliance.
 - c. Once the H&P Flex Rig is on location, it shall not be removed from over the hole without prior approval unless the production casing has been run and cemented or the well has been properly plugged. If the drilling rig is removed without approval an Incident of Non-Compliance will be written and will be a "Major" violation.
 - d. BOP/BOPE test to be conducted per Onshore Oil and Gas Order No. 2 as soon as H&P Flex Rig is rigged up on well. CIT for the surface casing shall be performed and results recorded on subsequent sundry pressure to be 1200 psi.

CRW 033011