Form 3160-5 (September 2001)

3a. Address

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

FORM APPROVED

## SUNDRY NOTICES AND REPORTS ON WELLS

	DEPARTMENT OF THE INTERIOR			OM B No. 1004-0135 Expires: January 31, 2004		
	BUREAU OF LAND MAN			5. Lease Serial l NM14293		
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an					6. If Indian, Allottee or Tribe Name	
	ell. Use Form 3160 - 3 (			o. n maan, r	Another of Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well ☐ Gas Well ☐ Other		RECEIVED		8. Well Name and No.		
2. Name of Operator Pecos River (	Operating	FFR 2 8 7004		Slayton Federal #1  9. API Well No.		
Sa. Address		3b. Phone No. (include area code) TESIA		30-005-61101		
4. Location of Well (Footage, Sec., 1		432-620-8480		10. Field and Pool, or Exploratory Area  Pecos Slope Abo		
660' FNL & 660' FWL, Sec 1-18S-26E			11. County or Parish, State			
				Chaves Co, NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION		ТҮРЕ	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Star	t/Resume)	Water Shut-Off	
	Alter Casing Casing Repair	Fracture Treat	Reclamation	L T	Well Integrity Other	
Subsequent Report	Change Plans	New Construction Plug and Abandon	Recomplete Temporarily Aba	ındon	Ouler	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
Attach the Bond under which the following completion of the invitesting has been completed. Findetermined that the site is ready 12/12/03- MIRU BCM Set 12/17/03- Circ btms up. M 4415'. Plug #1 from 4799'	ctionally or recomplete horizontally as work will be performed or provious olved operations. If the operation all Abandonment Notices shall be for final inspection.)  rvices. ND WH & NU BOP's. Aix mud & pmp in hole. Set 2-4415', BLM rep (Stan Mayes)	ly, give subsurface locations ide the Bond No. on file wit results in a multiple completified only after all requirement. Pull 4 jts of 2 3/8" tbg. 25 sxs cmt plg. TOOH to so on loc & witnessed plu	and measured and true th BLM/BIA. Required tion or recompletion in ents, including reclamate 3000' no drag on the	vertical depths of I subsequent rept a new interval, a tion, have been o	of all pertinent markers and 2 orts shall be filed within 30 of Form 3160-4 shall be filed completed, and the operator I	zones. lays once has
12/24/03- TIH & tag plug 12/25/03- TIH & perf csg (	rom, 2262'-2162' & TOOH w @ 2160'. TOOH, perf csg @ @ 100'. Nipple 4 ¼" csg swag nors, clean loc & install dry ho	1180', set 25 sxs plug . ? ge. Break circ out 8 5/8"	- circ cmt to surf (4			

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	<u> </u>							
Dora Lara	Title I	Engr Asst						
Signature Zara Zara	Date	2-24-04						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by New CD		Title	Date					
Conditions of approval, if any, are attached conditions of this notice does not warra certify that the applicant holds legal a conduct operations thereon.	ease	Office						
Titl. 19 LLC C. Serie 1991 and Title 42 LLC C. Series 1212 and bit a mine for any negro beautingly and will fully to make to any department or agree up of the United								