and the second of the second o	*.	
Submit 1 Copý To Appropriate District State of Ne	w Mexico	Form C-103
Office District I Energy, Minerals and	Natural Resources	October 13, 2009 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240  District II  1301 W. Grand Ave. Artesia, NM 88210  OIL CONSERVA	LION DIVISION	30-015-23481 ~
1301 W. Grand Ave., Artesia, NM 88210 District III  1220 South St		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, N		STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		·
SUNDRY NOTICES AND REPORTS ON W		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Gissler AV   8. Well Number
PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other		8. Well Number
2. Name of Operator		9. OGRID Number
Yates Petroleum Corporation ✓ 3. Address of Operator		10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 88210		Eagle Creek San Andres
4. Well Location		4.
Unit Letter G: 1650 feet from the North line and 2310 feet from the East line		
Section 23 Township 17S Range 25E NMPM Eddy County  11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
11. Elevation (Show Wheth	3491' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:	SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐		
	☐ CASING/CEME	
DOWNHOLE COMMINGLE		<del>-</del>
OTHER:	□ OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
<ol> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1243'. Spot a 90 sx class "C" cement plug from 1243' to surface. This will fill the entire well bore up from the</li> </ol>		
CIBP to the surface. WOC and tag plug.		
3. Cut off wellhead and install dry hole marker. Clean up	location as per regulation	ns.
SEE ATTACHED		DECEIVED
CONDITIONS OF NO	otify OCD 24 hrs	s. prior RECEIVED
_	To any work do	MAY 13 2011
APPROVAL		NMOCD ARTESIA
		NIVIOCE ATTIZENS
Spud Date: Rig Re	lease Date:	
I hereby certify that the information above is true and complete	to the best of my knowled	lge and belief.
,		
SIGNATURE TITLE	Regulatory Compliance	ce Technician DATE May 12, 2011
Type or print name <u>Craig Aton</u> E-mail add	lress: caton@yatespetro	Noum com DHONE: 575 749 4295
Type or print name Craig Aton E-mail add  For State Use Only	iress. <u>caton@yatespetro</u>	<u>oleum.com</u> PHONE: <u>575-748-4385</u>
Matuber		DATE 6/11/2011
APPROVED BY: TITLE Conditions of Approval (if any):	Approval Granted providi	ng work DATE 5/16/20//
	Approval Granted providing is complete by	( <del>)</del>
		l <sub>a</sub>



