

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD - Artesia

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

NM 35607

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

S.C. WILLIAMSON

3a. Address

Box 16 MIDLAND TX

3b. Phone No. (include area code)

432-682-1797

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1287' FSL/330' FWL S25/T26S/R29E

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

WCBNW #9

9. API Well No.

30-015-25529

10. Field and Pool or Exploratory Area

11. Country or Parish, State

EDDY CO NM


12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. The proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 day following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

- 1 SET CIBP @ 3050 SPOT 25 SK PLUG TAG PLUG
- 2 SET 25 SK PLUG @ 1855 TAG PLUG
- 3 CUT 4 1/2 CSG @ 1000' Pull out of hole w CSG
- 4 SET 50 SK PLUG @ 1145' TAG PLUG TOP @ 955'
- 5 SET 500' SURFACE PLUG. 170 SKS.
- 6 ERECT DRY HOLE MARKER
7. CLEAN & RIP LOC
8. RESEED PER BLM REC

C.R.C. NOIE W/ FRESH
WATER GEL BETWEEN
ALL PLUGS



14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)

DARELL FOIMAR

Title

Agent

Signature

Darell Foimar

Date

5/12/11

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

At 5/31/2011

Accepted for record
NMOCD