MSZ N French Dr. Hobbs, NM 8240 Date of the Construction Division Santa Fe, NM 87505 Sund Fe, NM 87505	Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 Revised June 10, 2003		
1. 1. 1. 1. 1. 1. 1. 1.		5. 7		WELL API NO		
Santa Fe, NM 87505 Santa Fe, NM 87505 6. State Oil & Gas Lease No. 1208 St. Francis Dr., Senta Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOTICISE THIS FORM FOR PROPOSALS TO DRILLON TO DEEPEN OR PLUG BACK TO A DEPFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-10) FOR SUCH PROPOSALS) 1. Type of Well: Oil Well Gas Well X Other RECEIVED 2. Name of Operator Yates Petroleum Corporation MAR - 8 7000 3. Address of Operator Yates Petroleum Corporation Unit Letter P : 660 feet from the South line and 660 feet from the East line Section 36 Township 68 Range 26E NMPM Chaves County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.447-GR 1. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND CAMPANDON CAMPANDON CAMPANDON ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT COMPLETION OTHERS: Recompletion X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Complications: Attach wellbore diagram of proposed completion or recompletion. 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Complications: Attach wellbore diagram of proposed completion or recompletion. 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Complications: Attach wellbore diagram of proposed completion or recompletion. 14. Type or print name Tina Huerta E-mail address: tinah@ypenm.com Telephone No. 505-748-1471 15. The print name Tina Huerta E-mail address: tinah@ypenm.com Telephone No. 505-748-1471	District III	1220 South St. Francis Dr.				
SUNDRY NOTICES AND REPORTS ON WELLS OD NOT USE THIS FORM FOR PROPOSALS TO DAILL OR TO DEFERN OR PHUG BACK TO A DEFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: Oil Well Gas Well C Other RECEIVED Oil Well Gas Well C Other Other Other Other Yates Petroleum Corporation MAR - 8 7004 9. OGRID Number 1. Address of Operator OSS755 3. Address of Operator OSS755 4. Well Location Unit Letter Gas Well Location Unit Letter Gas Gas Gas Gas Gas Gas Gas Gas Gas	District IV	bistrict IV Santa Fe, NW 87505				
OD NOT USE THIS FORM FOR PROPOSALS TO DEBLEM OR PLUG BACK TO A DEFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: Oil Well Gas Well X Other RECEIVED 1	87505					
RECEIVED 1 2008 1 2009 20	(DO NOT USE THIS FORM FOR PROPOSAL	_				
Oil Well	PROPOSALS.)		***			
Yates Petroleum Corporation	Oil Well Gas Well X Other RECEIVED					
3. Address of Operator 105 S. 4th Street, Artesia, NM 88210 4. Well Location Unit Letter P: 660 feet from the South line and 660 feet from the East line Section 36 Township 6S Range 26E NMPM Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3847'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER CASING MULTIPLE COMPLETION TO THERE ABANDON TO THERE Recompletion TEMPORARILY ABANDON SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 14. Total Acidize Silurian with 3000g 20% IC acid and 80 balls. 220-22/04 — Set CIBP at 5990' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 2720'04 — Acidize Mississippian with 2000g 20% IC acid and 2000 SCF N2/bbl. 15. TITLE: Regulatory Compliance Supervisor DATE: March 3, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 TITLE: Regulatory Compliance Supervisor DATE: March 3, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471		MAI	R - 8 2004		F	
4. Well Location Unit Letter P: 660 feet from the South line and 660 feet from the East line Section 36 Township 6S Range 26E NMPM Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3847GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: Recompletion THER: Recompletion THER: Recompletion THER: Recompletion THER: Activities Silurian with 3000g 20% IC acid and 80 balls. 2/20-2/204 - Set CIBP at 6960 with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 - Acidize Mississippian with 2000g 20% IC acid and 2200 SCF N2/bbl. 2/23/04 - Acidize Mississippian with 2000g 20% IC acid and 2200 SCF N2/bbl. 2/27/04 - Acidize Cisco with 200 cement on top. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5790'-5706' (14), and 5730'-5736' (14). 2/27/04 - Acidize Cisco with 2000g 15% IC acid and 2000 SCF/bbl. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: The Arch 3, 2004 TITLE: Regulatory Compliance Supervisor DATE: March 3, 2004 Type or print name Tina Huerta E-mail address: tinab@ypcnm.com Telephone No. 505-748-1471 This space for State use)	3. Address of Operator	3. Address of Operator OCD-ARTESIA		10. Pool name or Wildcat		
Unit Letter P : 660 feet from the South line and 660 feet from the East line Section 36 Township 68 Range 26E NMPM Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3847'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDON ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT COMPLETION CEMENT JOB OTHER: OTHER: OTHER Recompletion X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/04 - Acidize Silurian with 3000g 20% IC acid and 80 balls. 2/20-22/04 - Set CIBP at 6660' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 - Set CIBP at 6660' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 - Acidize Mississippian with 2000g 20% IC acid and 2000 SCF N2/bbl. 2/26/04 - Set CIBP at 5900' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5700'-5706' (14), and 5730'-5736' (14). 2/27/04 - Acidize Cisco with 2000g 15% IC acid and 2000 SCF/bbl. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: A march 3, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 This space for State use)		Hay	stack Cisco			
Section 36 Township 6S Range 26E NMPM Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3847'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ABANDON ABANDONMENT COMMENCE DRILLING OPNS PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: CASING TEST AND CEMENT JOB OTHER: Recompletion X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/04 - Acidize Silurian with 3000g 20% IC acid and 80 balls. 2/20-2/204 - Set CIBP at 6060' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 - Acidize Mississippian with 2000g 20% IC acid and 2200 SCF N2/bbl. 2/26/04 - Set CIBP at 5990' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5700'-5706' (14), and 5730'-5736' (14). Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: A TITLE: Regulatory Compliance Supervisor DATE: March 3, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 This space for State use)	4. Well Location					
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3847'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Recompletion X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/04 - Acidize Silurian with 3000g 20% IC acid and 80 balls. 2/20-22/04 - Set CIBP at 6060' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 - Acidize Mississippian with 2000g 20% IC acid and 2200 SCF N2/bbl. 2/26/04 - Set CIBP at 5990' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5700'-5706' (14), and 5730'-5736' (14). 2/27/04 - Acidize Cisco with 2000g 15% IC acid and 2000 SCF/bbl. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE:	Unit Letter P : 660	feet from the South	line and66	feet from the	ne <u>East</u> line	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Recompletion X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/04 - Acidize Silurian with 3000g 20% IC acid and 80 balls. 2/20-22/04 - Set CIBP at 6060' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 - Acidize Mississippian with 2000g 20% IC acid and 2200 SCF N2/bbl. 2/26/04 - Set CIBP at 5090' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5700'-5706' (14), and 5730'-5736' (14). 2/27/04 - Acidize Cisco with 2000g 15% IC acid and 2000 SCF/bbl. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE:	Section 36	Township6S Ran	age <u>26E</u>	NMPMChav	es County	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND ABANDONMENT COMPLETION TOTAL RECOMPLETION CASING TEST AND CEMENT JOB OTHER: TOTAL RECOMPLETION TOTAL RECOMPLETION TOTAL RECOMPLETION TOTAL RECOMPLETION TOTAL RECOMPLETION 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/04 - Acidize Silurian with 3000g 20% IC acid and 80 balls. 2/20-22/04 - Set CIBP at 6060' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 - Acidize Mississippian with 2000g 20% IC acid and 2200 SCF N2/bbl. 2/26/04 - Set CIBP at 5990' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5700'-5706' (14), and 5730'-5736' (14). 2/27/04 - Acidize Cisco with 2000g 15% IC acid and 2000 SCF/bbl. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE:						
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS ABANDON ABANDON CHANGE PLANS COMMENCE DRILLING OPNS ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: Recompletion X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/04 — Acidize Silurian with 3000g 20% IC acid and 80 balls. 2/220-22/04 — Set CIBP at 6060' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 — Set CIBP at 5990' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5700'-5706' (14), and 5730'-5736' (14). 2/27/04 — Acidize Cisco with 2000g 15% IC acid and 2000 SCF/bbl. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 3, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 This space for State use)						
PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Recompletion 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/04 - Acidize Silurian with 3000g 20% IC acid and 80 balls. 2/20-22/04 - Set CIBP at 6060' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 - Acidize Mississippian with 2000g 20% IC acid and 2200 SCF N2/bbl. 2/26/04 - Set CIBP at 5990' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5700'-5706' (14), and 5730'-5736' (14). 2/27/04 - Acidize Cisco with 2000g 15% IC acid and 2000 SCF/bbl. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: Acidize March 3, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)						
PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Recompletion 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/04 - Acidize Silurian with 3000g 20% IC acid and 80 balls. 2/20-22/04 - Set CIBP at 6060' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 - Acidize Mississippian with 2000g 20% IC acid and 2200 SCF N2/bbl. 2/26/04 - Set CIBP at 5990' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5700'-5706' (14), and 5730'-5736' (14). 2/27/04 - Acidize Cisco with 2000g 15% IC acid and 2000 SCF/bbl. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 3, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)	TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL	LING OPNS.		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/04 — Acidize Silurian with 3000g 20% IC acid and 80 balls. 2/20-22/04 — Set CIBP at 6060' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 — Acidize Mississippian with 2000g 20% IC acid and 2200 SCF N2/bbl. 2/26/04 — Set CIBP at 5990' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5700'-5706' (14), and 5730'-5736' (14). 2/27/04 — Acidize Cisco with 2000g 15% IC acid and 2000 SCF/bbl. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 3, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 MAR 1 1 2004				D 🗌	ADANDONWENT	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/04 – Acidize Silurian with 3000g 20% IC acid and 80 balls. 2/20-22/04 – Set CIBP at 6060' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 – Acidize Mississippian with 2000g 20% IC acid and 2200 SCF N2/bbl. 2/26/04 – Set CIBP at 5990' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5700'-5706' (14), and 5730'-5736' (14). 2/27/04 – Acidize Cisco with 2000g 15% IC acid and 2000 SCF/bbl. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 3, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)	OTHER:		OTHER: Recompl	etion	X	
2/20-22/04 – Set CIBP at 6060' with 20' cement on top. Perforate Mississippian 5996'-6022' (104). 2/23/04 – Acidize Mississippian with 2000g 20% IC acid and 2200 SCF N2/bbl. 2/26/04 – Set CIBP at 5990' with 35' cement. Perforate Cisco 5582'-5588' (14), 5592'-5598' (14), 5628'-5634' (14), 5674'-5682' (18), 5700'-5706' (14), and 5730'-5736' (14). 2/27/04 – Acidize Cisco with 2000g 15% IC acid and 2000 SCF/bbl. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 3, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)	of starting any proposed work)		ertinent details, and	give pertinent date	es, including estimated date	
SIGNATURE: TITLE: Regulatory Compliance Supervisor DATE: March 3, 2004 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use)	2/20-22/04 – Set CIBP at 6060' with 20 2/23/04 – Acidize Mississippian with 20 2/26/04 – Set CIBP at 5990' with 35' ce 5700'-5706' (14), and 5730'-5736' (14)	o' cement on top. Perforate Missi 000g 20% IC acid and 2200 SCF ement. Perforate Cisco 5582'-55).	N2/bbl.	` ,	4' (14), 5674'-5682' (18),	
Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 (This space for State use) MAR 1 1 2004					ATE: March 2 2004	
(This space for State use) MAR 1 1 2004)		-	-		
MAR 1 1 2004		E-mail ad	Idress: tinah@ypcn	m.com Tel		
Conditions of approval, if any:	APPPROVED BY	R RECORDS ONLY			MAR I 1 2004 _DATE	