

Mr J L Hunter
State Oil & Gas Inspect
Carlsbad N Mex.

Roswell N Mex
Aug 19 1932

Dear Sir:

Please send me blank for abandon well and please
advise me on requirements I would like to proceed
to pull pipe shot lets than Red. next week
My plan is to pull up hole to bottom of $5\frac{3}{4}$
with a good shale mud then pull $5\frac{3}{4}$ then fill with
mud by running back in to prevent bridging
to bottom of 8 in at 6.88 then pull 8 in and continue
filling to top of 10 in then pull 10 and get to top
of hole. Please advise if any change in method
I want to abandon well according to law
I am preparing report and log and will mail
tomorrow

Yours Truly
O. J. Herman