

PLUGS AND ADAPTERS

Heaving plug—Material _____ Length _____ pth set _____

Adapters—Material _____ Size _____

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
100 qts.	4 1/2"	Nitroglycerin		8-13	1250'	1280'
120 "	"	" "		8-17	1250'	1280'

TOOLS USED

Rotary tools were used from 0 feet to 1105 feet, and from _____ feet to _____ feet

Cable tools were used from 1105 feet to 1283 feet, and from _____ feet to _____ feet

DATES

Shut in Sept. 10, 1936 Put to producing _____, 19____

The production for the first 24 hours was 6 barrels of fluid of which 100 % was oil; _____ % emulsion; _____ % water; and _____ % sediment. Gravity, ~~35~~ A.P.I. 35.8

If gas well, cu. ft. per 24 hours _____ Gallons gasoline per 1,000 cu. ft. of gas _____

Rock pressure, lbs. per sq. in. _____

EMPLOYEES

R.D. Hill _____, Driller _____, Driller

Nay Hightower _____, Driller _____, Driller

FORMATION RECORD

FROM	TO	TOTAL FEET	FORMATION
0	10	10	Soil
10	25	25	Red Bed
25	100	100	Anhydrite
100	110	110	Gravel
110	205	205	Red Bed
205	240	240	Shale
240	330	330	Red Bed
330	495	495	Blue Shale
495	555	555	Red Gravel & Sand
555	755	755	Anhydrite
755	1283	1283	Lime

(OVER)