(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

sand Office Las Cruces Lease No. 026468 (a) Unit Sloop & Brosli

	and the control of th
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS.	
NOTICE OF INTENTION TO TEST WATER SH	
NOTICE OF INTENTION TO RE-DRILL OR RE	1 1
NOTICE OF INTENTION TO SHOOT OR ACID] []
NOTICE OF INTENTION TO PULL OR ALTER	, <u> </u>
NOTICE OF INTENTION TO ABANDON WELL	<u> </u>
(INDICATE ABO	OYE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)
	September 9 , 194
	d 510 ft. from N line and 660 ft. from E line of sec. 1
(% Sec. and Sec. No.)	(Twp.) (Range) (Meridian)
Comenates	Chaves New Maxico
(Field)	(County or Subdivision) (State or Territory)
itate names of and expected depths to obje	jective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cei ing points, and all other important proposed work)
Hole will be filled upward through tubin bole with coment ar	with mud and 25 sack coment plug placed at 900° ag. 8-5/8° easing (set at 755°) will be left in round the outside at surface. Marker will be welded to plug top of easing.
SEE ORIGINAL AFILIC. Hole will be filled upward through tubin bole with comen's ar-	with and and 25 sack coment plug placed at 900° and 8-5/8° casing (set at 755°) will be left in
Hole will be filled upward through tubin bole with comen's ar	with mud and 25 sack coment plug placed at 900° ag. 8-5/8° easing (set at 755°) will be left in round the outside at surface. Marker will be welded to plug top of easing.
Hole will be filled upward through tubin hole with cement are into tep of 8-5/8"	ATION MAI 7, 1947: With mid and 25 sack coment plug placed at 900' ing. 8-5/8" easing (set at 755') will be left in round the outside at surface. Marker will be welded to plug top of easing.
Hole will be filled upward through tubin hole with cement are into top of 8-5/8"	With mid and 25 sack coment plug placed at 900° ag. 8-5/8° easing (set at 755°) will be left in cound the cutside at surface. Marker will be welded to plug top of easing.
Hole will be filled upward through tubin hole with cement are into top of 8-5/8"	with and and 25 sack coment plug placed at 900° ag. 8-5/8° casing (set at 755°) will be left in round the outside at surface. Marker will be welded to plug top of casing.