(Fob. 1951)	Kosuell	Land Office	Las Cruces	
(SUB	BMIT IN TRIPLICATE)	·	063841-E	4
	NITED STATES	Lease No	••••••••••••••••••••••••••••••••••••••	
DEPARTM	IENT OF THE INTERIOR	Unit	R	ECEIN
	OLOGICAL SURVEY			
A Preil (A) E				
JAMERICT			•	SEP 221
	AND REPORTS OF	N WELL		O. C. C
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATE	R SHUT-OFF		
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOT	TING OR ACIDIZING		-
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTER	RING CASING		•
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DR	RILLING OR REPAIR		t. E
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANI			
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	Y		
NOTICE OF INTENTION TO ABANDON WELL				
	MARK NATURE OF REPORT, NOTICE, OR OTHE	ER DATA)		
	MARK RATORE OF REPORT, NOTICE, OR OTHE		,	
	March	27	19.58	•
Federal Withers Lease				
Well No. 1-26 is located 1980 ft. 1	from $\begin{bmatrix} N \\ \infty \end{bmatrix}$ line and $_$ 160 ft. ft	$\operatorname{rom}_{XXX}^{\{E\}}$ line	of sec. <u>26</u>	
SE/4NE/4 Sec. 26 129 (1/ Sec. and Sec. No.) (Twp.)	26E N.M.P.M. (Range) (Meridian)	*****		
exter San Andres Chaves	New Mexi	00		
(Pield) (Oo The elevation of the derrick floor above se	a level is <u>3577</u> ft. ground	(State or Territor	(7	
				1
DE	TAILS OF WORK			
		asings; indicate m	udding jobs, coment-	
(State names of and expected depths to objective sand: ; shing points, and ing points, and ing points, and the set of the	ow sizes, weights, and lengths of proposed of all other important proposed work) A off at 9631 and pulled.	- · ·	udding jobs, comont-	
(State names of and expected depths to objective sand: ; shing points, and ing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug	ow sizes, weights, and lengths of proposed of d all other important proposed work) 1 off at 9631 and pulled. through 2" tubing, 13703	- · ·	udding jobs, comonto	
(State names of and expected depths to objective sand: , shing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370") - 940'. Tu tubing, 940-885 in bot	- 1130'.	3/4"	
(State names of and expected depths to objective sand:, shing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. ru tubing, 940885 in bot se in top of 10 3/4" and	- 1130'. tom of 10 erected ma	3/4"	
(State names of and expected depths to objective sand: , shi ing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. ru tubing, 940885 in bot se in top of 10 3/4" and	- 1130'. tom of 10 erected ma	3/4"	
(State names of and expected depths to objective sand:, shing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. ru tubing, 940885 in bot se in top of 10 3/4" and	- 1130'. tom of 10 erected ma	3/4"	
(State names of and expected depths to objective sand:, shing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. ru tubing, 940885 in bot se in top of 10 3/4" and	- 1130'. tom of 10 erected ma	3/4"	
(State names of and expected depths to objective sand:, shing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. ru tubing, 940885 in bot se in top of 10 3/4" and	- 1130'. tom of 10 erected ma	3/4"	
(State names of and expected depths to objective sand:, shing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. ru tubing, 940885 in bot se in top of 10 3/4" and	- 1130'. tom of 10 erected ma	3/4"	
State names of and expected depths to objective sand: , shi ing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface fork completed 3-4-58. Location i	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. Tu tubing, 940-885 in bot is in top of 10 3/4" and is now ready for inspecti	- 1130'. tom of 10 erected ma on.	3/4" rker pipe.	
(State names of and expected depths to objective sand: ; shing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface fork completed 3-4-58. Location i	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. Tu tubing, 940-885 in bot is in top of 10 3/4" and is now ready for inspecti	- 1130'. tom of 10 erected ma on.	3/4" rker pipe.	
(State names of and expected depths to objective sand: , shi ing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface fork completed 3-4-58. Location i understand that this plan of work must receive appro Company John Ha. Trigg	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. Tu tubing, 940-885 in bot is in top of 10 3/4" and is now ready for inspecti	- 1130'. tom of 10 erected ma on.	3/4" rker pipe.	
State names of and expected depths to objective sand: , shifts well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface fork completed 3-4-58. Location i I understand that this plan of work must receive appro Company John Ha. Trigg. P. O. Box 5629	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. Tu tubing, 940-885 in bot is in top of 10 3/4" and is now ready for inspecti	- 1130'. tom of 10 erected ma on.	3/4" rker pipe.	
State names of and expected depths to objective sand: , shifts well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface fork completed 3-4-58. Location i I understand that this plan of work must receive appro Company John Ha. Trigg. P. O. Box 5629	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. Tu tubing, 940-885 in bot is in top of 10 3/4" and is now ready for inspecti	- 1130'. tom of 10 erected ma on.	3/4" rker pipe.	
(State names of and expected depths to objective sand: ; shing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface Nork completed 3-4-58. Location i i understand that this plan of work must receive appro CompanyJohn Ha. Trigg P. O. Box 5629 Address	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. Tu tubing, 940-885 in bot is in top of 10 3/4" and is now ready for inspecti	- 1130'. tom of 10 erected ma on.	3/4" rker pipe.	
(State names of and expected depths to objective sand: ; shing points, and his well was plugged as follows: 1. 5 1/2" casing was knocked 2. Pumped in a 30 sack plug 3. Filled hole with mud 1130 4. Pumped a 30 sack plug thr 5. Set 3 sack plug at surface fork completed 3-4-58. Location i lunderstand that this plan of work must receive appro CompanyJohn Ha Trigg P. 0. Box 5629 Address	ow sizes, weights, and lengths of proposed of d all other important proposed work) through 2" tubing, 1370")' - 940'. Tu tubing, 940-885 in bot is in top of 10 3/4" and is now ready for inspecti	- 1130'. tom of 10 erected ma on.	3/4" rker pipe.	

.