Well now plugged back to 2126' in 42" casing. 13-3/8" casing at 225'.

It is proposed to plug and abandon well as follows:

Mud hole. Spot 5 sacks of cement from 2126 to 2076'. Cut and pull 43" casing (estimated at 1000 to 1500'). Spot 23 sacks of cement from 25' inside pipe cut to 25' above pipe. Spot 40 sacks of cement from 950' to 900'. Spot 74 sacks of cement from 700 to 610' (12-1/4" hole). Spot 40 sacks of cement from 250' to 200'. Put cement plug in top of 13-3/8" casing with 4" pipe marker.

		RECEIVED
I understand	that this plan of work must receive approval in writ	ing by the Geological Survey before operations may be commenced.
Company	Harry L. Bigbee	DEC -8 1961
Address	Box 669	U. S. GEGLEGICAL SUBVEY
	Santa Pe, New Mexico	By Ralph L Fray
		Title Consulting Engineer.
		GPQ 862040