

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Division

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE


1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM-19837
2. Name of Operator McCellan Oil Corp.	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P.O. Drawer 730 Roswell, NM 88202-0730 505/622-3200	7. If Unit or CA, Agreement Designation CA-NM061P3586C341
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660 FSL & 660 FWL SEC 9-T4S-R27E	8. Well Name and No. MOC. WHITE Fed.Com#1
	9. API Well No. 30-005-00216
	10. Field and Pool, or Exploratory Area w/c Mississippian
	11. County or Parish, State Chaves County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) Set CIBP @ 6225 +35' cmt
 - 2) Circ hole w/10# Brine Gell
 - 3) Spot 25sx "C" 4750-4470
 - 4) Perf 4 1/2 casing @ 1535'
 - 5) Spot 35sx "C" @ 1535-1415 (inside & behind 4 1/2 casing) Tag Plug.
 - 6) Spot 15sx "C" 50'-surface (in & behind 4 1/2 casing)
 - 7) Clean location & level P.T.
- See attached drawing of well bore before & after.



14. I hereby certify that the foregoing is true and correct

Signed William R. Homer Title Agent Date 04-13-98

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any: