| NG. OF COPIES RECEIVED | 3 | | |
|--------------------------------------|---------|---|--------------------------------|
| DISTRIBUTION | | | Form C-103 Supersedes Old |
| SANTA FE | 1 | NEW MEXICO OIL CONSERVATION CONVERSION | C-102 and C-103 |
| FILE | 1 | NEW MEXICO OIL CONSERVATION COMMISSION | Effective 1-1-65 |
| U.S.G.S. | | | |
| LAND OFFICE | + | | 5a. Indicate Type of Lease |
| OPERATOR | 1 | RECEIVED | State Fee |
| | 1./ | | 5. State Oil & Gas Lease No. |
| (DO NOT USE THIS FO USE | SUNDR | Y NOTICES AND REPORTS ON WELLSMARNI 5 SERVICE OF FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. | | | 7. Unit Agreement Name |
| OIL GAS WELL WELL | | OTHER- D. C. C. | |
| 2. Name of Operator | | ARTESIA, DEFILE | 8. Farm or Lease Name |
| Michols & Brady Production Company 🗸 | | | Nc Intyre-State |
| 3. Address of Operator | | | 9. Well No. |
| P. O. Box 197 | 2. yidi | and, Texas 79702 | • |
| 4. Location of Well | | | 10. Field and Pool, or Wildcat |
| UNIT LETTER | 1 | 650 FEET FROM THE NOTED LINE AND 330 FEET FRO | |
| | | n 4 township 85 range 27E nmpn | |
| | | 15. Elevation (Show whether DF, RT, GR, etc.) 3976 GL | 12. County Chaves |
| 16. | Check / | | |
| NOTIC | | Appropriate Box To Indicate Nature of Notice, Report or O | |
| | | SUBSEQUEN | IT REPORT OF: |
| PERFORM REMEDIAL WORK | | PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| TEMPOPARILY ABANDON |] | COMMENCE DRILLING OPNS. | PLUG AND ABANDONMENT |
| PULL OR ALTER CASING |] | CHANGE PLANS CASING TEST AND CEMENT JOB | FLOG AND ABANDONMENT [|
| | | | |
| | | OTHER | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

December 16, 1977 through February 7, 1978

- 1. Rigged up pulling unit. Found pump stuck, could not pull. Found tubing stuck, could not pull.
- 2. Backed off rods & using fishing socked made several trips and recovered all rdds, leaving 10° pump and 5° pony rod in hole.
- 3. Ran McCullough chemical cutter and cut tubing at 1916' leaving 1-1/2 jts. tbg. in hole.
- 4. Ran 3-3/16 ID wash pipe on 2-3/8 tubing. Rigged up small rotary rig and washed over fish an recovered same.
- 5. Ran 5 jts. 2-1/16 Intergal joint tbg. on bottom 6 57 Jts. of 2-3/8 tbg. Ran rods and pump. Started well pumping using batch treatment scale inhibitor down casing. Pump stuck in 11 days.
- 6. Pulled rods and tubing, stripping tubing over stuck rods.
- 7. Reran rods and tubing and pumped well down.
- 8. Squeezed pay section with 35 gallons of Hallibuton LP 55 scale inhibitor mixed in 25 bbls. of fresh water and displaced with 120 bbls. of produced water
- 9. Shut well in for 48 hours.
- 10. Placed on production. Request an allowable of 10 BOPD for the months of March & April 1978 until fresh production decreases and 5 BOPD thereafter.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. Sale Michols TITLE PAREDER DATE March 14, 1978 With Williams TITLE OIL AND GAS INSPECTOR DATE MAR 1 7 1978 CONDITIONS OF APPROVAL, IF AN