

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-101  
Effective 1-1-66

5a. Well Name	
5b. Well No.	
5c. Well Type	
5d. Well Status	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- DRY HOLE <input checked="" type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Ernest A. Hanson			8. Well Owner Name
3. Address of Operator P. O. Box 1515, Roswell, New Mexico			9. Well No.
4. Location of Well UNIT LETTER M, 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 12, TOWNSHIP 12-S, RANGE 27-E, N.M.P.M.			10. Field and Pool, or Wildcat
11. Elevation (Show whether DF, RT, CR, etc.) 3808'			12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Permission to plug and abandon the captioned well in the following manner is hereby requested:

Pull approximately 1450' of 5-1/2" casing.

Set cement plugs as follows:

1. Set 25 sx. cement plug @ T.D. to cover perfs. 2195-2513'.
2. Set 25 sx. cement plug @ stub of 5-1/2" casing.
3. Set 5 sx. cement plug @ surface & erect regulation marker.

Clean-up location for final N.M.O.C.C. inspection.

RECEIVED

FEB 21 1966

O. C. C.  
ARTERIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lucy F. Johnson TITLE Geologist DATE 2/17/66

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE FEB 21 1966

CONDITIONS OF APPROVAL, IF ANY: