40. OF COPIES RECEIVED				Form C-103	
	DISTRIBUTION DESCRIPTION OF THE PLANT OF THE			Supersedes Old C-102 and C-103	
SANTA FE				Effective 1-1-65	
!LE				a talenta Transacti acces	
U.S.G.S.		APR 2	2 0 1971	5a. Indicate Type of Lease State Fee. X	
LAND OFFICE	1-1-1		. 0		
OPERATOR	+ - +	-		5. State Oil & Gas Lease No.	
	المسلما		C. C.		
0.6			t, office		
(DO NOT USE THIS FO	SUNDK	Y NOTICES AND REPORTS ON WELL POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO ON FOR PERMIT - " (FORM C-101) FOR SUCH PROP	L D DIFFERENT RESERVOIR.		
	**APPLICATI	ON FOR PERMIT -" (FORM C-101) FOR SUCH PROP	USALS./	7. Unit Agreement Name	
l. OIL GAS	\Box	Do completion			
WELL X WELL OTHER- RE-COMPTECTOR				8. Form or Lease Name	
2. Name of Operator				O'Brien C	
t winlakes 0il Company ✓				9. Well No.	
3. Address of Operator				2	
P. O. Box 1582, Roswell, N. M. 88201				10. Field and Pool, or Wildcat	
4. Location of Well				Twin Lakes San Andres	
D 660 North LINE AND 660 FEET FROM				M IWIII Lakes Sall Allares	
• • • • • • • • • • • • • • • • • • • •					
THE West LINE, SECTION 1 TOWNSHIP 9 S. RANGE 28 E. NMPM.					
THE WEST LINE, SECTION TOWNSHIP				THE PARTY OF THE P	
mmmm	mm	15. Elevation (Show whether DF, R	RT, GR, etc.)	12. County	
		3944 KB		Chaves ()	
	777777		CN .: Dimant as O	the Data	
16.	Check	Appropriate Box To Indicate Natur	e of Notice, Report of U	ther Data	
NOT	ICE OF I	TENTION TO:	SUBSEQUEN	T REPORT OF:	
			—	_	
PERFORM REMEDIAL WORK		PLUG AND ABANDON REN	MEDIAL WORK	ALTERING CASING	
Ē	=	CON	MMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON	-	CHANGE PLANS CAS	SING TEST AND CEMENT JOB		
PULL OR ALTER CASING			OTHER		
OTHER					
La Describe Desponed or (Completed O	perations (Clearly state all pertinent details,	and give pertinent dates, includi	ng estimated date of starting any propose	
work) SEE RULE 1103	i.	,			
3,	/24 /71 -	Pulled tubing. Set Halli wire line at 2600'. Ran nipple at 2545-49. Acidi acid with 420 gallons ove pressure 1200# - Treated Swabbed load and acid res salt water cut 10-20% v it Ran rods and put on pump	ized with 3000 gallowerflush (lease crude at 1000# at 3 BPM. sidue - 92 bbls - + th oil. 3/25/71.	ns regular). Maximum <i>F3 2569-92</i> — 100 bbls.	
	on4-15-71 Pump 11BC + 40BW 34hr.				
		Bn4-15-71 Pump 116	30 + 40 Du 27	737	
			w knowledge and helief.		
18. I hereby certify that t	he informati	on above is true and complete to the best of m	y knowledge and better		
•	17 1			p. 4 m 4 mg s	
* / · /	1 42	Com TITLE	Manager	DATE <u>4/15/71</u>	
SIGNED					
		1		APR 20 1971	
J. 1	11.	4nens XX	ND GAS INSPECTOR	APR 20 1971	
APPROVED BY	, 11,	PULLE UIL AI	IU GAS MISTEUI UR		

CONDITIONS OF APPROVAL, IF ANY: